

WORKOVER PROCEDURE

WELL NAME: REINICK 01 **DATE:** 4/8/2014
LOCATION:
Qtr/Qtr: SE/NE Section: 9 Township: 4N Range: 64W
Footages: 1650' FNL & 1050' FEL
COUNTY: WELD **STATE:** CO **API #:** 05-123-11316

ENGINEER: JONATHAN POMERANTZ 7 Day Notice Sent: _____
(Please notify Engineer of any major changes prior to work) Do not start operations until: _____
Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8" 24# @ 419' KB Elevation: 4700'
Surface Cmt: 450 sx GL Elevation: 4690'
Long St Csg: 4 1/2" 10.5# @ 7430' TD: 7448'
Long St Cmt: 250 sx PBTD: 6709'
Long St Date: 11/9/1983

Plug Back (Sand or CIBP): **Retrievable Bridge Plug @ 6719' w/ Sand Plug on top up to 6709'**
Perforation Interval (1): Codell Perforations 6848' - 6862'
Perforation Interval (2): J Sand Perforations 7310' - 7354'
Perforation Interval (3): _____
Tubing: _____ Rods: _____
Pump: _____
Misc.: **CIBP @ 7240' w/ 2 sx Cement on top and Sand Plug up to 6752'**

PRODUCTION STATUS: _____
COMMENTS: _____

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) RIH w/ workstring and retrieving head.
- 3) Wash down, tag sand (approx 6709'). Circulate clean to RBP, latch on, POOH w/ RBP.
- 4) RIH w/ workstring. Wash down, tag sand (approx 6752'). Circulate clean to 6850'. POOH w/ workstring.
- 5) RU WL. RIH w/ CIBP. Set CIBP @ 6798', dump bail 2 sx of cement on top.
- 6) Unland casing. Cut casing off @ 4600'. POOH with casing laying down on trailer.
- 7) RIH w/ workstring to pump 125 sx stub plug where csg was pulled. If maintain circulation, do not need to tag plug.
- 8) Pump 50 sx courtesy plug @ 2500'. POOH w/workstring to 520'. Pump approx 175 sx shoe plug. Cement to surface.
- 9) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 10) Cut surface casing off 6'-8' below ground.
- 11) Clean up location. Reclaim location. RDMO.