

## WORKOVER PROCEDURE

**WELL NAME:** CANNON H34-25 **DATE:** 4/23/2014  
**LOCATION:**  
Qtr/Qtr: SW/SW Section: 34 Township: 3N Range: 65W  
Footages: 1320' FSL 1320' FWL  
**COUNTY:** WELD **STATE:** CO **API #:** 05-123-23250

**ENGINEER:** JONATHAN POMERANTZ 7 Day Notice Sent: \_\_\_\_\_  
(Please notify Engineer of any major changes prior to work) Do not start operations until: \_\_\_\_\_  
Notice Expires: \_\_\_\_\_

**OBJECTIVE:** P&A

**WELL DATA:**  
Surface Csg: 8 5/8" 24# @ 677' KB Elevation: 4844'  
Surface Cmt: 515 sx GL Elevation: 4834'  
Long St Csg: 4 1/2" 11.6# @ 7226' TD: 7280'  
Long St Cmt: 600 sx PBTD: 7214'  
Long St Date: 10/10/2005

Plug Back (Sand or CIBP): \_\_\_\_\_  
Perforation Interval (1): Niobrara Perforations 6884' - 6902'  
Perforation Interval (2): Codell Perforations 7129' - 7142'  
Perforation Interval (3): \_\_\_\_\_  
Tubing: 2 3/8" 4.7# J-55 @ 7090' Rods: \_\_\_\_\_  
Pump: \_\_\_\_\_  
Misc.: \_\_\_\_\_

**PRODUCTION STATUS:** \_\_\_\_\_  
**COMMENTS:** \_\_\_\_\_

### PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) Control well with 2% KCl water if needed. Ensure hole is full of fluid.
- 3) N/D wellhead. N/U BOP.
- 4) POOH w/ 2 3/8" tbg and lay down.
- 5) RIH w/ workstring and retrievable bridge plug. Set RBP @ 6834'.
- 6) Pressure up on the casing to 2000 psi for 15 minutes (Verify pressure does not exceed MAOP, reduce as necessary).
  - a) If casing fails to hold pressure, continue with procedure below.
  - b) If casing pressure holds, call office for orders (Janelle S - 970-304-5157; Jonathan P - 970-304-5222).
- 7) RIH w/ workstring and retrieving head. Latch on to RBP @ 6834'. POOH w/ workstring and RBP.
- 8) RU WL. RIH w/CIBP. Set CIBP @ 6834', dump bail 2 sx of cement on top.
- 9) Unland casing. Cut casing off @ 3900'. POOH with casing laying down on trailer.
- 10) RIH w/ workstring to pump 100 sx stub plug where csg was pulled. If maintain circulation, do not need to tag plug.
- 11) Pump 50 sx courtesy plug @ 2500'. POOH w/workstring to 780'. Pump approx 250 sx shoe plug. Cement to surface.
- 12) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 13) Cut surface casing off 6'-8' below ground.
- 14) Clean up location. Reclaim location. RDMO.