

Recommended Plug and Abandonment Procedure
Box Elder H 3
SWNW Section 31, T1S, R65W
API# 05-001-09410

1. MIRU. ND WH. NU BOP.
2. TOOH w/ 2-3/8" tbg, inspect and tally.
3. MIRU wireline RIH w/ perforating guns and shoot 4 holes @ 1,610' MD. TOH w/ perf guns. TIH w/ 4-1/2" CICR and set @ 1,510' MD. TOH w/ setting tool and RDMO wireline.
4. TIH w/ tbg and sting into CICR. Establish circulation through braden head **(contact office if circulation through braden head cannot be established)**. Mix and pump 63 sks of Class G, 14.8 ppg, 1.15 yield cement into CICR. Pull out of CICR and leave 5 sks of Class G, 14.8 ppg, 1.15 yield cement on top of CICR to cover surface casing shoe. Pull tbg above cement and reverse circulate to clean up tbg. TOH w/ tbg and LD stinger. **Wait 4 hrs and TIH w/ tbg to tag plug and verify cement top.**
5. TIH w/ tbg open ended to 100' MD. Pump 10 sks Class G, 14.8 ppg, 1.15 Yield cement to surface for the surface plug. Pull tubing out of hole. Top off casing w/ cement if needed.
6. SI well and WOC.
7. ND BOP and cut off casing below surface casing flange. Install P&A marker w/ cement to comply w/ regulations.
8. RD and move off location. Cut off anchors and restore location.