

## WORKOVER PROCEDURE

**WELL NAME:** OSTER PMG28-08 **DATE:** 5/15/2014  
**LOCATION:**  
Qtr/Qtr: SE/NE Section: 28 Township: 4N Range: 65W  
Footages: 1800' FNL & 600' FEL  
**COUNTY:** WELD **STATE:** CO **API #:** 05-123-14152

**ENGINEER:** JONATHAN POMERANTZ 7 Day Notice Sent: \_\_\_\_\_  
(Please notify Engineer of any major Do not start operations until: \_\_\_\_\_  
changes prior to work) Notice Expires: \_\_\_\_\_

**OBJECTIVE:** P&A

**WELL DATA:** Surface Csg: 8 5/8" 24# @ 310' KB Elevation: 4811'  
Surface Cmt: 165 sx GL Elevation: 4798'  
Long St Csg: 2 7/8" ?# @ 7338' TD: 7365'  
Long St Cmt: 270 sx PBTD: 7194'  
Long St Date: 2/5/1989

Plug Back (Sand or CIBP): \_\_\_\_\_  
Perforation Interval (1): Niobrara Perforations 6898' - 7059'  
Perforation Interval (2): \_\_\_\_\_  
Perforation Interval (3): \_\_\_\_\_  
Tubing: No tubing data available Rods: \_\_\_\_\_  
Pump: \_\_\_\_\_  
Misc.: \_\_\_\_\_

**PRODUCTION STATUS:** \_\_\_\_\_  
**COMMENTS:** \_\_\_\_\_

### PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ tbq and lay down.
- 3) RU WL. RIH w/CIBP. Set CIBP @ 6848', dump bail 2 sx of cement on top.
- 4) Unland casing. Cut casing off @ 4600'. POOH with casing laying down on trailer.
- 5) RIH w/ workstring to pump 125 sx stub plug where csg was pulled. If maintain circulation, do not need to tag plug.
- 6) Pump 50 sx courtesy plug @ 2500'. POOH w/workstring to 630'. Pump approx 200 sx shoe plug. Cement to surface.
- 7) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 8) Cut surface casing off 6'-8' below ground.
- 9) Clean up location. Reclaim location. RDMO.