

FORM  
6Rev  
12/05State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE ET OE ES

Document Number:

400610250

Date Received:

05/16/2014

## WELL ABANDONMENT REPORT

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set.

A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

OGCC Operator Number: 47120

Contact Name: CHERYL LIGHT

Name of Operator: KERR MCGEE OIL &amp; GAS ONSHORE LP

Phone: (720) 929-6461

Address: P O BOX 173779

Fax: (720) 929-7461

City: DENVER State: CO Zip: 80217-

Email: CHERYL.LIGHT@ANADARKO.COM

For "Intent" 24 hour notice required,

Name: Carlile, Craig

Tel: (303) 8942100

COGCC contact:

Email: craig.carlile@state.co.us

API Number 05-123-17773-00

Well Name: MCLAUGHLIN

Well Number: 33-8

Location: QtrQtr: NWSE Section: 8 Township: 3N Range: 67W Meridian: 6

County: WELD

Federal, Indian or State Lease Number:

Field Name: WATTENBERG

Field Number: 90750

☒ Notice of Intent to Abandon☐ Subsequent Report of Abandonment

## Only Complete the Following Background Information for Intent to Abandon

Latitude: 40.238226

Longitude: -104.911815

GPS Data:

Date of Measurement: PDOP Reading: GPS Instrument Operator's Name:

Reason for Abandonment: ☐ Dry ☒ Production for Sub-economic ☐ Mechanical Problems☐ OtherCasing to be pulled: ☒ Yes ☐ No Estimated Depth: 4340Fish in Hole: ☐ Yes ☒ No If yes, explain details belowWellbore has Uncemented Casing leaks: ☐ Yes ☒ No If yes, explain details below

Details:

## Current and Previously Abandoned Zones

Formation	Perf. Top	Perf. Btm	Abandoned Date	Method of Isolation	Plug Depth
CODELL	7132	7142			
NIOBRARA	6872	6942			

Total: 2 zone(s)

## Casing History

Casing Type	Size of Hole	Size of Casing	Weight Per Foot	Setting Depth	Sacks Cement	Cement Bot	Cement Top	Status
SURF	12+1/4	8+5/8	24	392	270	392	0	VISU
1ST	7+7/8	3+1/2	7.7	7,275	300	7,275	5,710	CBL

## Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth 6810 with 50 sacks cmt on top. CIBP #2: Depth 80 with 23 sacks cmt on top.  
CIBP #3: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top. CIBP #4: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top.  
CIBP #5: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set 300 sks cmt from 4390 ft. to 3730 ft. Plug Type: STUB PLUG Plug Tagged: ☐  
Set \_\_\_\_\_ sks cmt from \_\_\_\_\_ ft. to \_\_\_\_\_ ft. Plug Type: \_\_\_\_\_ Plug Tagged: ☐  
Set \_\_\_\_\_ sks cmt from \_\_\_\_\_ ft. to \_\_\_\_\_ ft. Plug Type: \_\_\_\_\_ Plug Tagged: ☐  
Set \_\_\_\_\_ sks cmt from \_\_\_\_\_ ft. to \_\_\_\_\_ ft. Plug Type: \_\_\_\_\_ Plug Tagged: ☐  
Set \_\_\_\_\_ sks cmt from \_\_\_\_\_ ft. to \_\_\_\_\_ ft. Plug Type: \_\_\_\_\_ Plug Tagged: ☐

Perforate and squeeze at \_\_\_\_\_ ft. with \_\_\_\_\_ sacks. Leave at least 100 ft. in casing \_\_\_\_\_ CICR Depth

Perforate and squeeze at \_\_\_\_\_ ft. with \_\_\_\_\_ sacks. Leave at least 100 ft. in casing \_\_\_\_\_ CICR Depth

Perforate and squeeze at \_\_\_\_\_ ft. with \_\_\_\_\_ sacks. Leave at least 100 ft. in casing \_\_\_\_\_ CICR Depth

(Cast Iron Cement Retainer Depth)

Set 340 sacks half in. half out surface casing from 860 ft. to 190 ft. Plug Tagged: ☒

Set \_\_\_\_\_ sacks at surface

Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: ☐ Yes ☒ No

Set \_\_\_\_\_ sacks in rat hole Set \_\_\_\_\_ sacks in mouse hole

### Additional Plugging Information for Subsequent Report Only

Casing Recovered: \_\_\_\_\_ ft. of \_\_\_\_\_ inch casing Plugging Date: \_\_\_\_\_

\*Wireline Contractor: \_\_\_\_\_ \*Cementing Contractor: \_\_\_\_\_

Type of Cement and Additives Used: \_\_\_\_\_

Flowline/Pipeline has been abandoned per Rule 1103 ☐ Yes ☐ No \*ATTACH JOB SUMMARY

Technical Detail/Comments:

2. MIRU slickline services. Pull bumper spring, tag bottom. RDMO SL.
3. Provide notice to COGCC prior to MIRU per Form 6 COA.
4. Notify IOC when rig moves on location to generate work order for flowline removal and one call for line locates.
5. Prepare location for base beam rig.
6. MIRU WO rig. Kill well; circulate as necessary, with water containing biocide. ND wellhead. NU BOP's. Unseat landing joint and lay down.
7. Place cement services on will call when rig moves on location, providing expected volumes of cement needed. (~ 50 sacks for NBCD plug; 300 sacks for SXSH plug, ~ 340 sacks for top plug). See attached WBD for cement blends.
8. TOOH and stand back 2-1/16" (3.25#) TBG.
9. MIRU wireline services. RIH gauge ring for 3-1/2"(7.7#) casing to 7000'.
10. PU 3-1/2" (7.7#) CIBP and RIH on W/L to +/- 6810'. Set CIBP. P/T CIBP to 1000 psi.
11. RIH on 2-1/16" TBG to +/- 6810'. Hydrotest TBG to 3000 psi while RIH.
12. Initiate circulation using water containing biocide. Note rate, pressure and circulation.
13. MIRU cementing services. Spot 50 sacks of "G" w/ 20% silica flour, 0.4% CD-32, 0.4% ASA-301 and R-3 to achieve 2:30 pump time mixed at 15.8 ppg and 1.15 cuft/sk. Cement from 6810' to 5710'.
14. PUH 26 stands. Circulate (2 X TBG Vol + Excess) to CLR TBG. RD cementing services
15. Load hole and circulate with 9.0 ppg mud containing biocide.
16. P & SB 4390' of tubing (70 stands). LD remainder.
17. RU wireline services. Crack closest coupling at 4340' or shoot off. RD wireline.
18. Circulate with mud w/ biocide to remove any gas from 3-1/2" and OH annulus.
19. NDBOP, NDTH.
20. NU BOP on casing head. Install 3-1/2" pipe rams.
21. TOOH with 3-1/2" casing and lay down.
22. RIH with 2-1/16" TBG into casing stub to +/- 4390'.
23. RU Cementing services. Preflush with 5 bbl of H2O; 20 bbl of sodium metasilicate; 5 bbl of H2O.
24. Pump 300 sacks of "G" w/ 0.25 pps cello flake , 0.4% CD-32, 0.4% ASA - 301, mixed at 15.8 ppg and 1.15 cuft/sk with 20% excess used and considering hole size of 9". Cement from 4390' to 3730'.
25. PUH to +/- 3730' or TOC. Circulate (2 X TBG Vol + Excess) to CLR TBG. RD cementing services.
26. Load hole and circulate with 9.0 ppg mud containing biocide.
27. PUH to 860'. LD remainder.
28. Initiate circulation using water containing biocide. Note rate, pressure and circulation.
29. MIRU cementing services.
30. Pump 340 sacks of Type III w/ cello flake and CaCl2, mixed at 14.0 ppg and 1.53 cuft/sk. Cement from 860' to 190'. Volumes calculated considering 12" hole size and 20% excess.
31. PUH to +/- 190'. Circulate w / 9.0 ppg mud + biocide to CLR TBG. TOOH . WOC 4 hrs.
32. TIH and tag cement plug. If plug top is below 190', top as necessary. RDMO cementing services.
33. MIRU wireline services. PU 8-5/8" CIBP and RIH to 80'. Set CIBP. Pressure test CIBP to 1000 psi for 15 minutes. If plug tests, RDMO wireline and WO rig.
34. Instruct cementing and wireline contractors to e-mail copies of all job logs/job summaries and invoices to rscDJVendors@anadarko.com within 24 hrs of the completion of the job.
35. Wellsite supervisor turn all paper copies of cementing reports/invoices and logs in to Joleen Kramer. NOTE: During the job, wellsite supervisor should instruct the logging and cementing contractors to e-mail all logs, job reports/invoices to Joleen Kramer.
36. Have excavation contractor notify One-Call to clear for excavating around wellhead and flowline removal.
37. Excavate hole around surface casing of sufficient size and depth to allow welder to cut off 8-5/8" surface casing and at least 5' below ground level.
38. Have welder cut off 8-5/8" surface casing at least 5' below ground level.
39. MIRU ready cement mixer. Use 4,500 psi compressive strength redi-mix cement (sand and cement only, no gravel) Fill STUB. RDMO cement services.
40. Have welder spot weld steel marker plate on top of surface casing. (Note: marker shall be labeled with well name and number, legal location (1/4 1/4 description) and API number.

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: \_\_\_\_\_ Print Name: CHERYL LIGHT  
 Title: SR. REGULATORY ANALYST Date: 5/16/2014 Email: DJREGULATORY@ANADARKO.COM

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: SCHLAGENHAUF, MARK Date: 5/23/2014

CONDITIONS OF APPROVAL, IF ANY: \_\_\_\_\_ Expiration Date: 11/22/2014

<u>COA Type</u>	<u>Description</u>
	1) Submit Form 42 electronically to COGCC 48 hours prior to MIRU. 2) If unable to pull casing, contact COGCC for plugging modifications. 3) For 860' plug: pump plug and displace. Wait 4 hours then tag plug – must be 340' or shallower. 4) Properly abandon flowlines as per Rule 1103. File electronic Form 42 once abandonment complete. 5) Operator must provide well location GPS coordinates on Subsequent Report of Abandonment in accordance with COGCC As-Built Location Policy and Rule 215. 6) Please submit gyro survey data with Form 6 (s) Subsequent Report of Abandonment.

### **Attachment Check List**

<u>Att Doc Num</u>	<u>Name</u>
400610250	FORM 6 INTENT SUBMITTED
400610252	PROPOSED PLUGGING PROCEDURE
400610253	WELLBORE DIAGRAM

Total Attach: 3 Files

### **General Comments**

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
Permit	Well Completion Report dated 4/04/1994.	5/20/2014 4:21:05 PM

Total: 1 comment(s)