

## WORKOVER PROCEDURE

**WELL NAME:** SHABLE K08-03 **DATE:** 6/9/2014  
**LOCATION:**  
Qtr/Qtr: NE/NW Section: 8 Township: 4N Range: 66W  
Footages: 661' FNL & 1926' FWL  
**COUNTY:** WELD **STATE:** CO **API #:** 05-123-20371

**ENGINEER:** JONATHAN POMERANTZ 7 Day Notice Sent: \_\_\_\_\_  
(Please notify Engineer of any major Do not start operations until: \_\_\_\_\_  
changes prior to work) Notice Expires: \_\_\_\_\_

**OBJECTIVE:** P&A

**WELL DATA:** Surface Csg: 8 5/8" 24# @ 402' KB Elevation: 4722'  
Surface Cmt: 296 sx GL Elevation: 4712'  
Long St Csg: 4 1/2" 11.6# @ 7341' TD: 7369'  
Long St Cmt: 180 sx + 250 sx PBTD: 7318'  
Long St Date: 10/9/2002

Plug Back (Sand or CIBP): \_\_\_\_\_  
Perforation Interval (1): Codell Perforations 7177' - 7192'  
Perforation Interval (2): \_\_\_\_\_  
Perforation Interval (3): \_\_\_\_\_  
Tubing: 2 3/8" 4.6# J-55 tbg @ 7164' Rods: \_\_\_\_\_  
Pump: \_\_\_\_\_  
Misc.: \_\_\_\_\_

**PRODUCTION STATUS:** \_\_\_\_\_  
**COMMENTS:** \_\_\_\_\_

### PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 2 3/8" tbg and lay down.
- 3) RU WL. RIH w/ CIBP. Set CIBP @ 7127', dump bail 2 sx of cement on top.
- 4) RIH w/ workstring to 4500'. Pump 30 sx balance plug. SI, WOC. RIH. Tag balance plug @ approx 4100'.
- 5) Unland casing. Cut casing off @ 2500'. POOH with casing laying down on trailer.
- 6) RIH w/ workstring to pump 100 sx stub/shoe plug where csg was pulled. If maintain circulation, no need to tag plug.
- 7) POOH w/ workstring to 510'. Pump 200 sx shoe plug. Cement to surface.
- 8) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 9) Cut surface casing off 6'-8' below ground.
- 10) Clean up location. Reclaim location. RDMO.