

WORKOVER PROCEDURE

WELL NAME: DINNER 01-02 **DATE:** 6/10/2014

LOCATION: Qtr/Qtr: NE/SE Section: 1 Township: 4N Range: 65W

Footages: 1920' FSL & 656' FEL

COUNTY: WELD **STATE:** CO **API #:** 05-123-12207

ENGINEER: JONATHAN POMERANTZ 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8" 24# @ 348' KB Elevation: 4821'
Surface Cmt: 200 sx GL Elevation: 4811'
Long St Csg: 4 1/2" 11.6# @ 7183' TD: 7200'
Long St Cmt: 180 sx PBTD: 7113'
Long St Date: 1/4/1985

Plug Back (Sand or CIBP): _____
Perforation Interval (1): Niobrara-Codell Perforations 6860' - 7083'
Perforation Interval (2): _____
Perforation Interval (3): _____
Tubing: 2 3/8" 4.7# J-55 tbg @ 7055' Rods: _____
Pump: _____
Misc.: _____

PRODUCTION STATUS: _____

COMMENTS: _____

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 2 3/8" tbg and lay down.
- 3) RU WL. RIH w/ CIBP. Set CIBP @ 6810', dump bail 2 sx of cement on top.
- 4) Unland casing. Cut casing off @ 4600'. POOH with casing laying down on trailer.
- 5) RIH w/ workstring to pump 125 sx stub/shoe plug where csg was pulled. If maintain circulation, no need to tag plug.
- 6) Pump 50 sx courtesy plug @ 2500'. POOH w/ workstring to 570'. Pump 225 sx shoe plug. Cement to surface.
- 7) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 8) Cut surface casing off 6'-8' below ground.
- 9) Clean up location. Reclaim location. RDMO.