

## WORKOVER PROCEDURE

**WELL NAME:** DINNER 01-44 **DATE:** 7/24/2014  
**LOCATION:**  
Qtr/Qtr: SE/SE Section: 1 Township: 4N Range: 65W  
Footages: 860' FSL & 460' FEL  
**COUNTY:** WELD **STATE:** CO **API #:** 05-123-17082

**ENGINEER:** JONATHAN POMERANTZ 7 Day Notice Sent: \_\_\_\_\_  
(Please notify Engineer of any major Do not start operations until: \_\_\_\_\_  
changes prior to work) Notice Expires: \_\_\_\_\_

**OBJECTIVE:** P&A

**WELL DATA:** Surface Csg: 8 5/8" 24# @ 449' KB Elevation: 4811'  
Surface Cmt: 300 sx GL Elevation: 4800'  
Long St Csg: 4 1/2" 15.1# @ 7229' TD: 7230'  
Long St Cmt: 200 sx PBTD: 7190'  
Long St Date: 7/18/1993

Plug Back (Sand or CIBP): \_\_\_\_\_  
Perforation Interval (1): Niobrara Perforations 6850' - 6980'  
Perforation Interval (2): Codell Perforations 7068' - 7078'  
Perforation Interval (3): \_\_\_\_\_  
Tubing: 2 3/8" ?# ? tbg @ 7034' Rods: \_\_\_\_\_  
Pump: \_\_\_\_\_  
Misc.: \_\_\_\_\_

**PRODUCTION STATUS:** \_\_\_\_\_  
**COMMENTS:** \_\_\_\_\_

### PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 2 3/8" tbg and lay down.
- 3) RU WL. RIH w/ CIBP. Set CIBP @ 6800', dump bail 2 sx of cement on top.
- 4) Unland casing. Cut casing off @ 4600'. POOH with casing laying down on trailer.
- 5) RIH w/ workstring to pump 125 sx stub plug where csg was pulled. If maintain circulation, no need to tag plug.
- 6) Pump 50sx Courtesy lug @2500'.
- 7) POOH w/ workstring to 550'. Pump 225 sx shoe plug. Cement to surface.
- 8) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 9) Cut surface casing off 6'-8' below ground.
- 10) Clean up location. Reclaim location. RDMO.