

WORKOVER PROCEDURE

WELL NAME: TURK WHITE D19-02 **DATE:** 7/30/2014

LOCATION: Qtr/Qtr: NW/NE Section: 19 Township: 3N Range: 64W

Footages: 510' FNL & 1980' FEL

COUNTY: WELD **STATE:** CO **API #:** 05-123-16293

ENGINEER: JONATHAN POMERANTZ 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8" 24# @ 528' KB Elevation: 4775'
Surface Cmt: 370 sx GL Elevation: 4763'
Long St Csg: 4 1/2" 10.5# @ 7162' TD: 7228'
Long St Cmt: 690 sx PBTD: 6961'
Long St Date: 3/27/1993

Plug Back (Sand or CIBP): _____
Perforation Interval (1): Sussex Perforations 4378' - 4417'
Perforation Interval (2): Codell Perforations 7024' - 7034'
Perforation Interval (3): _____
Tubing: 2 3/8" 4.7# ? tbg @ 6961' Rods: _____
Pump: _____
Misc.: _____

PRODUCTION STATUS: _____
COMMENTS: _____

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 2 3/8" tbg and lay down.
- 3) RU WL. RIH w/ CIBP. Set CIBP @ 6974', dump bail 2 sx of cement on top.
- 4) RIH w/ workstring to 5100'. Pump 70 sx balance plug. SI, WOC. RIH. Tag balance plug @ approx 4200'.
- 5) Unland casing. Cut casing off @ 2500'. POOH with casing laying down on trailer.
- 6) RIH w/ workstring to pump 100 sx stub plug where csg was pulled. If maintain circulation, no need to tag plug.
- 7) POOH w/ workstring to 730'. Pump 275 sx shoe plug. Cement to surface.
- 8) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 9) Cut surface casing off 6'-8' below ground.
- 10) Clean up location. Reclaim location. RDMO.