

## PLUG AND ABANDONMENT PROCEDURE (RE-ENTER)

HSR-SAWDY 14-36

- | Step | Description of Work   |
|------|---|
| 1    | Locate and expose 8 5/8" casing stub. Extend stub to surface and install 8 5/8"x 11" SOW, 3M casing head with 3000 psi ball valves in both outlets. Prepare location for workover rig. Install perimeter fence as needed.   |
| 2    | Provide notice to COGCC prior to rig up per request on approved Form 6 (e.g. call field coordinator, submit Form 42, etc.).   |
| 3    | MIRU workover rig. NU 9" 3000 psi BOP stack on casing head. PT BOP and csg head per approved Form 2. Function test BOPE . NU rotating head on BOP. Hook up return line to shale shaker on flat tank   |
| 4    | PU 7 7/8" mill tooth bit, necessary drill collars and drill pipe/work string (WS). Drill through existing cement plugs at surface (20 sk) and at the base of surface casing (100 sk plug ~340'-512') using fresh water with biocide.  |
| 5    | Once surface cement plugs are drilled, displace hole with drilling mud and RIH to stub of 4 1/2" casing @ 4095'. (There are discrepancies on depth of casing stub. RIH to 3374' slowly then continue slowly to RIH to 4095'). Tag casing stub and TOH and LD drill collars and bit.   |
| 6    | RIH WS open-ended to casing stub. Attempt to drift past stub by 100'. (Cement top in annulus is 4150'). Circulate and condition hole for additional cement plug.  |
| 7    | Run gyro survey from csg stub to surface.   |
| 8    | RU Cementers. Spot cement plug consisting of 100 sx (115 cu-ft) "G" w/0.25pps cello flake, 0.4% CD-32, 0.4% ASA-301 with CaCl <sub>2</sub> as necessary. Mixed at 15.8 ppg, 1.15 cuft/sack. Cement to be preceded by sodium metasilicate mixed in 20 bbls water per cementing company recommendation. Calculated top of plug 3950' based on 10" hole with 40% excess. (Caliper log from this well.) POH to ~2500' and circulate mud. WOC per cement company recommendation. |
| 9    | Tag top of plug at 3950'. LD WS to place end of WS at 1230'.  |
| 10   | Spot cement plug consisting of 500 sx (665 cu-ft) Type III w/cello flake and CaCl <sub>2</sub> as deemed necessary, mixed at 1.33 cf per sack, 14.8 ppg. POH and WOC per cementing company recommendation. Plug size is based on 10" hole with 40% excess covering 1230' to shoe of surface casing at 468' plus capacity of surface casing to 250'. TOH and WOC per cement company recommendation   |
| 11   | Tag top of plug at 250'. POOH and LD WS.  |
| 12   | RU wireline. Run and set CIBP in the 8 5/8", 24# surface casing at 80'. PT CIBP and surface casing to 1000 psi for 15 minutes. Assuming successful test, RD wireline.   |
| 13   | RDMO workover rig.  |

- 14 Instruct cementing and wireline contractors to e-mail copies of all job logs/job summaries to rscDJVendors@anadarko.com within 24 hrs of completion of the job.
- 15 Supervisor submit paper copies of all invoices, logs, and reports to Joleen Kramer.
- 16 Excavate hole around surface casing of sufficient size to allow welder to cut off 8 5/8" casing at least 5' Below ground level (depending on land owner requirements).
- 17 Fill surface casing with cement (4500 psi compressive strength, no gravel).
- 18 Spot weld steel marker plate on top of sfc casing stub. Marker shall be labeled with well name, well number, legal location (1/4 1/4 descriptor) and API number.
- 19 Obtain GPS location data as per COGCC Rule 215 and send to rscDJVendors@anadarko.com.
- 20 Back fill hole with native material. Reclaim location to landowner specifications
- 21 Submit Form 6 to COGCC. Provide "As plugged" wellbore diagram identifying the specific plugging completed.

Reed Boeger  
Sr. Production Engineer - GWA  
reed.boeger@anadarko.com  
970.506.5987 (work)  
512.217.1852 (cell)