

WORKOVER PROCEDURE

WELL NAME: M D RADKE 22-01 **DATE:** 9/17/2014

LOCATION:
Qtr/Qtr: SW/NW Section: 22 Township: 3N Range: 65W
Footages: 2040 FNL & 640 FWL

COUNTY: WELD **STATE:** CO **API #:** 05-123-14373

ENGINEER: JEREMY GILBERT 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8" 24# @ 515' KB Elevation: 4823'
Surface Cmt: 260 sx GL Elevation: 4813'
Long St Csg: 3 1/2" 9.3# @ 7300' TD: 7324'
Long St Cmt: 230 sx PBDT: 7170'
Long St Date: 8/25/1989

Plug Back (Sand or CIBP): _____
Perforation Interval (1): Niobrara Perforations 6928' - 7018'
Perforation Interval (2): Codell Perforations 7143' - 7164'
Perforation Interval (3): _____
Tubing: 2 1/16" ?# ?tbg @ 7130' Rods: _____
Pump: _____
Misc.: _____

PRODUCTION STATUS: _____
COMMENTS: _____

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 2 1/16" tbg and lay down.
- 3) RU WL. RIH w/ CIBP. Set CIBP @ 6878', dump bail 2 sx of cement on top.
- 4) Unland casing. Cut casing off @ 2500'. POOH with casing laying down on trailer.
- 5) RIH w/ workstring to pump 100 sx stub plug where csg was pulled. If maintain circulation, no need to tag plug.
- 6) POOH w/ workstring to 700'. Pump 260 sx shoe plug. Cement to surface.
- 7) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 8) Cut surface casing off 6'-8' below ground.
- 9) Clean up location. Reclaim location. RDMO.