

WORKOVER PROCEDURE

WELL NAME: ROBERT C NICE 22-01 **DATE:** 9/25/2014
LOCATION:
Qtr/Qtr: NW/SW Section: 22 Township: 3N Range: 65W
Footages: 2015 FSL & 625 FWL
COUNTY: WELD **STATE:** CO **API #:** 05-123-14257

ENGINEER: JEREMY GILBERT 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8" 24# @ 564' KB Elevation: 4819'
Surface Cmt: 320 sx GL Elevation: 4809'
Long St Csg: 3 1/2" 9.3# @ 7258' TD: 7277'
Long St Cmt: 225 sx PBTD: 7204'
Long St Date: 4/9/1989

Plug Back (Sand or CIBP): _____
Perforation Interval (1): Niobrara Perforations 6790' - 7050'
Perforation Interval (2): Codell Perforations 7122' - 7140'
Perforation Interval (3): _____
Tubing: 2 1/16" ?# IJ tbg @ 7118' Rods: _____
Pump: _____
Misc.: _____

PRODUCTION STATUS: _____
COMMENTS: _____

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 2 1/16" tbg and lay down.
- 3) RU WL. RIH w/ CIBP. Set CIBP @ 6740', dump bail 2 sx of cement on top.
- 4) Unland casing. Cut casing off @ 2500'. POOH with casing laying down on trailer.
- 5) RIH w/ workstring to pump 100 sx stub plug where csg was pulled. If maintain circulation, no need to tag plug.
- 6) POOH w/ workstring to 694'. Pump 263 sx shoe plug. Cement to surface.
- 7) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 8) Cut surface casing off 6'-8' below ground.
- 9) Clean up location. Reclaim location. RDMO.