

**WORKOVER PROCEDURE**

**WELL NAME:** SPIKE STATE H36-05 **DATE:** 10/1/2014

**LOCATION:** Qtr/Qtr: SW/NW Section: 36 Township: 3N Range: 65W

Footages: 1800' FNL & 465' FWL

**COUNTY:** WELD **STATE:** CO **API #:** 05-123-16309

**ENGINEER:** JONATHAN POMERANTZ 7 Day Notice Sent: \_\_\_\_\_  
(Please notify Engineer of any major Do not start operations until: \_\_\_\_\_  
changes prior to work) Notice Expires: \_\_\_\_\_

**OBJECTIVE:** P&A

**WELL DATA:** Surface Csg: 8 5/8" 24# @ 533' KB Elevation: 4836'  
Surface Cmt: 300 sx GL Elevation: 4823'  
Long St Csg: 2 7/8" 6.5# @ 7252' TD: 7252'  
Long St Cmt: 240 sx PBTD: 7122'  
Long St Date: 1/19/1993

Plug Back (Sand or CIBP): \_\_\_\_\_  
Perforation Interval (1): Codell Perforations 7098' - 7108'  
Perforation Interval (2): \_\_\_\_\_  
Perforation Interval (3): \_\_\_\_\_  
Tubing: 1.66" 2.3# J-55 @ 7060' Rods: \_\_\_\_\_  
Pump: \_\_\_\_\_  
Misc.: \_\_\_\_\_

**PRODUCTION STATUS:** \_\_\_\_\_

**COMMENTS:** \_\_\_\_\_

**PROCEDURE:**

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 1.66" tbg and lay down.
- 3) RU WL. RIH w/ CIBP. Set CIBP @ 7048', dump bail 2 sx of cement on top.
- 4) Unland casing. Cut casing off @ 4600'. POOH with casing laying down on trailer.
- 5) RIH w/ workstring to pump 125 sx stub plug where csg was pulled. If maintain circulation, no need to tag plug.
- 6) Pump 50 sx courtesy plug @ 2500. POOH w/ workstring to 650'. Pump 250 sx shoe plug. Cement to surface.
- 7) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 8) Cut surface casing off 6'-8' below ground.
- 9) Clean up location. Reclaim location. RDMO.