

## WORKOVER PROCEDURE

**WELL NAME:** DOMENICO MC33-16X **DATE:** 10/14/2014  
**LOCATION:**  
Qtr/Qtr: SE/SE Section: 33 Township: 1N Range: 69W  
Footages: 574 FSL: & 559 FEL  
**COUNTY:** BOULDER **STATE:** CO **API #:** 05-013-06466

**ENGINEER:** JEREMY GILBERT 7 Day Notice Sent: \_\_\_\_\_  
(Please notify Engineer of any major Do not start operations until: \_\_\_\_\_  
changes prior to work) Notice Expires: \_\_\_\_\_

**OBJECTIVE:** P&A

**WELL DATA:** Surface Csg: 8 5/8" 24# @ 923' KB Elevation: 5368'  
Surface Cmt: 370 sx GL Elevation: 5358'  
Long St Csg: 3 1/2" 7.7# @ 8395' TD: 8440'  
Long St Cmt: 210 sx PBTD: 8367'  
Long St Date: 6/30/1994

Plug Back (Sand or CIBP): \_\_\_\_\_  
Perforation Interval (1): Niobrara Perforations 7852' - 8020'  
Perforation Interval (2): Codell Perforations 8259' - 8269'  
Perforation Interval (3): \_\_\_\_\_  
Tubing: 2" 3.25# J-55 tbq @ 8185' Rods: \_\_\_\_\_  
Pump: \_\_\_\_\_  
Misc.: \_\_\_\_\_

**PRODUCTION STATUS:** \_\_\_\_\_  
**COMMENTS:** \_\_\_\_\_

### PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 2" tbq and lay down.
- 3) RU WL. RIH w/ CIBP. Set CIBP @ 7802', dump bail 2 sx of cement on top.
- 4) Unland casing. Cut casing off @ 2500'. POOH with casing laying down on trailer.
- 5) RIH w/ workstring to pump 100 sx stub plug where csg was pulled. If maintain circulation, no need to tag plug.
- 6) POOH w/ workstring to 973'. Pump 385 sx shoe plug. Cement to surface.
- 7) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 8) Cut surface casing off 6'-8' below ground.
- 9) Clean up location. Reclaim location. RDMO.