

WORKOVER PROCEDURE

WELL NAME: MOSER H34-03 **DATE:** 11/5/2014
LOCATION:
Qtr/Qtr: NE/NW Section: 34 Township: 3N Range: 65W
Footages: 661 FNL & 1994 FWL
COUNTY: WELD **STATE:** CO **API #:** 05-123-15449

ENGINEER: JEREMY GILBERT 7 Day Notice Sent:
(Please notify Engineer of any major changes prior to work) Do not start operations until:
Notice Expires:

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8" 24# @ 519' KB Elevation: 4836'
Surface Cmt: 250 sx GL Elevation: 4826'
Long St Csg: 2 7/8" 8.7# @ 7293' TD: 7342'
Long St Cmt: 300 sx PBTD: 7170'
Long St Date: 12/11/1991

Plug Back (Sand or CIBP):
Perforation Interval (1): Codell Perforations 7134' - 7146'
Perforation Interval (2):
Perforation Interval (3):
Tubing: 1 2/3" 2.3# J-55 tbq @ 7110' Rods:
Pump:
Misc.:

PRODUCTION STATUS:
COMMENTS:

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 1 2/3" tbq and lay down.
- 3) RU WL. RIH w/ CIBP. Set CIBP @ 7084', dump bail 2 sx of cement on top.
- 4) Unland casing. Cut casing off @ 4500'. POOH with casing laying down on trailer.
- 5) RIH w/ workstring to pump 100 sx stub plug where csg was pulled. If maintain circulation, no need to tag plug.
- 6) POOH w/ workstring to 2500'. Pump 50 sx Courtesy Plug.
- 7) POOH w/ workstring to 792'. Pump 290 sx shoe plug. Cement to surface.
- 8) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 9) Cut surface casing off 6'-8' below ground.
- 10) Clean up location. Reclaim location. RDMO.