

WORKOVER PROCEDURE

WELL NAME: WAGNER 30-33 **DATE:** 12/8/2014
LOCATION:
Qtr/Qtr: SW/SW Section: 30 Township: 7N Range: 64W
Footages: 472 FSL & 491 FWL
COUNTY: WELD **STATE:** CO **API #:** 05-123-24808

ENGINEER: JEREMY GILBERT 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8" 24# @ 647' KB Elevation: 4860'
Surface Cmt: 290 sx GL Elevation: 4848'
Long St Csg: 4 1/2" 11.6# @ 7295' TD: 7300'
Long St Cmt: 635 sx PBTD: 7260'
Long St Date: 4/6/2007

Plug Back (Sand or CIBP): _____
Perforation Interval (1): Codell Perforations 7190' - 7206'
Perforation Interval (2): _____
Perforation Interval (3): _____
Tubing: 2 3/8" 4.7# J-55 tbg @ 7173' Rods: _____
Pump: _____
Misc.: _____

PRODUCTION STATUS: _____
COMMENTS: _____

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 2 3/8" tbg and lay down.
- 3) RU WL. RIH w/ CIBP. Set CIBP @ 7140', dump bail 2 sx of cement on top.
- 4) Unland casing. Cut casing off @ 2500'. POOH with casing laying down on trailer.
- 5) RIH w/ workstring to pump 100 sx stub plug where csg was pulled. If maintain circulation, no need to tag plug.
- 6) POOH w/ workstring to 736'. Pump 300 sx shoe plug. Cement to surface.
- 7) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 8) Cut surface casing off 6'-8' below ground.
- 9) Clean up location. Reclaim location. RDMO.