

WORKOVER PROCEDURE

WELL NAME: GUTTERSEN USX CC17-09 **DATE:** 12/9/2014

LOCATION:
Qtr/Qtr: NESE Section: 17 Township: 4N Range: 63W
Footages: 990 FSL & 990 FWL

COUNTY: WELD **STATE:** CO **API #:** 05-123-26254

ENGINEER: JANELLE SHABLE 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8" 24# @ 517' KB Elevation: 4734
Surface Cmt: 270 sx GL Elevation: 4724
Long St Csg: 4 1/2" 11.6# @ 7295' TD: 7300
Long St Cmt: 850 sx PBTD: 7247
Long St Date: 9/16/2007

Plug Back (Sand or CIBP): _____
Perforation Interval (1): JSand Perforations 7148' - 7184'
Perforation Interval (2): _____
Perforation Interval (3): _____
Tubing: 2 3/8" 4.7# J-55 tbg @ 7129' Rods: _____
Pump: _____
Misc.: _____

PRODUCTION STATUS: _____

COMMENTS: _____

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 2 3/8" tbg and lay down.
- 3) RU WL. RIH w/ CIBP. Set CIBP @ 7098', dump bail 2 sx of cement on top.
- 4) Unland casing. Cut casing off @ 2500'. POOH with casing laying down on trailer.
- 5) RIH w/ workstring to pump 100 sx stub plug where csg was pulled. If maintain circulation, no need to tag plug.
- 6) POOH w/ workstring to 617'. Pump 192 sx shoe plug. Cement to surface.
- 7) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 8) Cut surface casing off 6'-8' below ground.
- 9) RDMO. Clean up location. Reclaim location.