

WORKOVER PROCEDURE

WELL NAME: UPRC 17-15Q DATE: 12/8/2014

LOCATION: Qtr/Qtr: SW/SE Section: 17 Township: 2N Range: 64W

Footages: 990' FSL & 1650' FEL

COUNTY: WELD STATE: CO API #: 05-123-16729

ENGINEER: JONATHAN POMERANTZ 7 Day Notice Sent: (Please notify Engineer of any major changes prior to work) Do not start operations until: Notice Expires:

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8" 24# @ 803' KB Elevation: 4886' Surface Cmt: 360 sx GL Elevation: 4875' Long St Csg: 4 1/2" 11.6# @ 7633' TD: 7645' Long St Cmt: 285 sx PBTD: 7569' Long St Date: 2/10/1993

Plug Back (Sand or CIBP): Perforation Interval (1): J Sand Perforations 7541' - 7561' Perforation Interval (2): Perforation Interval (3): Tubing: None Rods: Pump: Misc.: HIC blown during casing pressure test, depths unknown

PRODUCTION STATUS: COMMENTS:

PROCEDURE:

- 1) MIRU Workover rig, pump & tank. 2) RIH w/ workstring to 7540' and circulate to clean out mud in hole. POOH w/ workstring once returns are clean. 3) RU WL. RIH w/ CIBP. Set CIBP @ 7491', dump bail 2 sx of cement on top. 4) RIH w/ perf gun. Perforate 4 1/2" csg @ 4500'. 5) RIH w/ CICR. Set CICR @ 4400'. Pump 240 sx through and 60 sx on top. 6) Unland casing. Cut casing off @ 2500'. POOH with casing laying down on trailer. 7) RIH w/ workstring to pump 100 sx stub plug where csg was pulled. If maintain circulation, no need to tag plug. 8) POOH w/ workstring to 980'. Pump 375 sx shoe plug. Cement to surface. 9) SI, WOC. RIH. Tag shoe plug. Add cement if needed. 10) Cut surface casing off 6'-8' below ground. 11) Clean up location. Reclaim location. RDMO.