

WORKOVER PROCEDURE

WELL NAME: JOHNSON 02 **DATE:** 12/16/2014
LOCATION:
Qtr/Qtr: NE/SE Section: 11 Township: 6N Range: 66W
Footages: 1980 FSL & 660 FEL
COUNTY: WELD **STATE:** CO **API #:** 05-123-12389

ENGINEER: JOHN HATCH 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8" 24# @ 306' KB Elevation: 4824'
Surface Cmt: 250 sx GL Elevation: 4813'
Long St Csg: 4 1/2" 11.6# @ 7348' TD: 7352'
Long St Cmt: 260 sx PBTD: 7310'
Long St Date: 4/20/1985

Plug Back (Sand or CIBP): _____
Perforation Interval (1): Codell Perforations 7255' - 7266'
Perforation Interval (2): _____
Perforation Interval (3): _____
Tubing: 2 3/8" 4.7# J-55 tbg @ 7231' Rods: _____
Pump: _____
Misc.: _____

PRODUCTION STATUS: _____
COMMENTS: _____

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 2 3/8" tbg and lay down.
- 3) RU WL. RIH w/ CIBP. Set CIBP @ 7205', dump bail 2 sx of cement on top.
- 4) Unland casing. Cut casing off @ 2500'. POOH with casing laying down on trailer.
- 5) RIH w/ workstring to pump 125 sx stub plug where csg was pulled. If maintain circulation, no need to tag plug.
- 6) POOH w/ workstring to 582'. Pump 225 sx shoe plug. Cement to surface.
- 7) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 8) Cut surface casing off 6'-8' below ground.
- 9) Clean up location. Reclaim location. RDMO.