

## WORKOVER PROCEDURE

**WELL NAME:** Peppler 17-33 **DATE:** 12/18/2014  
**LOCATION:**  
Qtr/Qtr: SWSW Section: 17 Township: 6N Range: 63W  
Footages: 478 FSL & 466 FWL  
**COUNTY:** WELD **STATE:** CO **API #:** 05-123-24309

**ENGINEER:** Narayan (Sonu) Choudhary 7 Day Notice Sent: \_\_\_\_\_  
(Please notify Engineer of any major Do not start operations until: \_\_\_\_\_  
changes prior to work) Notice Expires: \_\_\_\_\_

**OBJECTIVE:** P&A

**WELL DATA:** Surface Csg: 8 5/8" 24# @ 479' KB Elevation: 4677'  
Surface Cmt: 240 sx GL Elevation: 4665'  
Long St Csg: 4 1/2" 11.60# @ 6856' TD: 6896'  
Long St Cmt: 1330 sx PBTD: 6864'  
Long St Date: 11/26/2008

Plug Back (Sand or CIBP): \_\_\_\_\_  
Perforation Interval (1): Codell Perforations 6786' to 6795'  
Perforation Interval (2): \_\_\_\_\_  
Perforation Interval (3): \_\_\_\_\_  
Tubing: 2 3/8" ?# ?tbq @ 6762' Rods: \_\_\_\_\_  
Pump: \_\_\_\_\_  
Misc.: \_\_\_\_\_

**PRODUCTION STATUS:** \_\_\_\_\_  
**COMMENTS:** \_\_\_\_\_

### PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 2 3/8" tbq and lay down.
- 3) RU WL. RIH w/ CIBP. Set CIBP @ 6736', dump bail 2 sx of cement on top POOH
- 4) RIH w/workstring to 580'. Pump 25 sks of cmt. SI WOC. Tag cmt @ 272'
- 5) RIH w/Perf gun, perforate 4 1/2" csg @ 250'. POOH
- 6) RIH w/CICR. Set set CICR @ 172'. Pump 100sk through and 15 sks on top
- 7) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 8) Cut surface casing off 6'-8' below ground.
- 9) Clean up location. Reclaim location. RDMO.