

WORKOVER PROCEDURE

WELL NAME: STATE 36-11E DATE: 12/29/2014
LOCATION: Qtr/Qtr: NE/SW Section: 36 Township: 4N Range: 67W
Footages: 2183 FSL & 1798 FWL

COUNTY: WELD STATE: CO API #: 05-123-16745

ENGINEER: JEREMY GILBERT 7 Day Notice Sent:
(Please notify Engineer of any major Do not start operations until:
changes prior to work) Notice Expires:

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8" 23# @ 655' KB Elevation: 4780'
Surface Cmt: 440 sx GL Elevation: 4769'
Long St Csg: 2 7/8" 6.5# @ 7394' TD: 7409'
Long St Cmt: 200 sx PBTD: 7333'
Long St Date: 2/18/1993

Plug Back (Sand or CIBP):
Perforation Interval (1): Codell Perforations 7276' - 7295'
Perforation Interval (2):
Perforation Interval (3):
Tubing: 1 1/2" 2.76# J-55 tbg @ 7250' Rods:
Pump:
Misc.:

PRODUCTION STATUS:
COMMENTS:

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
2) POOH w/ 1 1/2" tbg and lay down.
3) RU WL. RIH w/ CIBP. Set CIBP @ 7226', dump bail 2 sx of cement on top.
4) Unland casing. Cut casing off @ 2500'. POOH with casing laying down on trailer.
5) RIH w/ workstring to pump 125 sx stub plug where csg was pulled. If maintain circulation, no need to tag plug.
6) POOH w/ workstring to 755'. Pump 320 sx shoe plug. Cement to surface.
7) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
8) Cut surface casing off 6'-8' below ground.
9) Clean up location. Reclaim location. RDMO.