

**WORKOVER PROCEDURE**

**WELL NAME:** ART RED D09-03J **DATE:** 12/31/2014

**LOCATION:** Qtr/Qtr: SW/SW Section: 9 Township: 3N Range: 64W

Footages: 990 FSL & 990 FWL

**COUNTY:** WELD **STATE:** CO **API #:** 05-123-16284

**ENGINEER:** JEREMY GILBERT 7 Day Notice Sent: \_\_\_\_\_  
(Please notify Engineer of any major Do not start operations until: \_\_\_\_\_  
changes prior to work) Notice Expires: \_\_\_\_\_

**OBJECTIVE:** P&A

**WELL DATA:** Surface Csg: 8 5/8" 24# @ 457' KB Elevation: 4744'  
Surface Cmt: 140 sx GL Elevation: 4733'  
Long St Csg: 2 7/8" 6.5# @ 4511' TD: 7552'  
Long St Cmt: 520 sx PBTD: 4335'  
Long St Date: 11/16/1992

Plug Back (Sand or CIBP): \_\_\_\_\_  
Perforation Interval (1): Sussex Perforations 4283' - 4331'  
Perforation Interval (2): \_\_\_\_\_  
Perforation Interval (3): \_\_\_\_\_  
Tubing: 2 1/16" 3.25# ?tbg @ 4154' Rods: \_\_\_\_\_  
Pump: \_\_\_\_\_  
Misc.: \_\_\_\_\_

**PRODUCTION STATUS:** \_\_\_\_\_  
**COMMENTS:** \_\_\_\_\_

**PROCEDURE:**

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 2 1/16" tbg and lay down.
- 3) RU WL. RIH w/ CIBP. Set CIBP @ 4233', dump bail 2 sx of cement on top.
- 4) Unland casing. Cut casing off @ 2500'. POOH with casing laying down on trailer.
- 5) RIH w/ workstring to pump 125 sx stub plug where csg was pulled. If maintain circulation, no need to tag plug.
- 6) POOH w/ workstring to 623'. Pump 250 sx shoe plug. Cement to surface.
- 7) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 8) Cut surface casing off 6'-8' below ground.
- 9) Clean up location. Reclaim location. RDMO.