

WORKOVER PROCEDURE

WELL NAME: STROH N35-09 (FKA 35-02) **DATE:** 1/14/2015
LOCATION:
Qtr/Qtr: NE/SE Section: 35 Township: 5N Range: 67W
Footages: 834' FSL & 2175' FWL
COUNTY: WELD **STATE:** CO **API #:** 05-123-13033

ENGINEER: GREG J ANDERSON 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8" 24# j-55 set @ 302' KB Elevation: 4869'
Surface Cmt: 210 sx to surface GL Elevation: 4858'
Long St Csg: 4 1/2" 11.6# N-80 set @ 7437' TD: 7455'
Long St Cmt: 236 sx PBTD: 7415'
Long St Date: 3/14/1986

Plug Back (Sand or CIBP): _____
Perforation Interval (1): Niobrara Perforations: 7002' - 7216'
Perforation Interval (2): Codell Perforations: 7328' - 7343'
Perforation Interval (3): _____
Tubing: _____ Rods: _____
Pump: _____
Misc.: TOC @ 6420'

PRODUCTION STATUS: _____
COMMENTS: _____

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 2 3/8" tbg and lay down.
- 3) RU WL. RIH w/ CIBP. Set CIBP @ 6978', dump bail 2 sx of cement on top.
- 4) Unland casing. Cut casing off @ 2500'. POOH with casing laying down on trailer.
- 5) RIH w/ workstring to pump 100 sx stub plug where csg was pulled. If maintain circulation, no need to tag plug.
- 6) POOH w/ workstring to 655' (150' below Fox Hills). Pump 250 sx shoe plug. Cement to surface.
- 7) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 8) Cut surface casing off 6'-8' below ground.
- 9) Clean up location. Reclaim location. RDMO.