

## WORKOVER PROCEDURE

**WELL NAME:** Farr 03 **DATE:** 1/28/2015  
**LOCATION:**  
Qtr/Qtr: SW/SE Section: 12 Township: 6 N Range: 66 W  
Footages: 660 FSL: & 1980 FEL  
**COUNTY:** WELD **STATE:** CO **API #:** 05-123-12141

**ENGINEER:** John Hatch 7 Day Notice Sent: \_\_\_\_\_  
(Please notify Engineer of any major Do not start operations until: \_\_\_\_\_  
changes prior to work) Notice Expires: \_\_\_\_\_

**OBJECTIVE:** P&A

**WELL DATA:** Surface Csg: 8 5/8" 24# @ 295' KB Elevation: 4800'  
Surface Cmt: 250 sx GL Elevation: 4788'  
Long St Csg: 4 1/2" 11.60# J-55 @ 7282' TD: 7286'  
Long St Cmt: 225 sx PBTD: 7248'  
Long St Date: 12/21/1984

Plug Back (Sand or CIBP): \_\_\_\_\_  
Perforation Interval (1): Codell Perforations 7192' - 7202'  
Perforation Interval (2): \_\_\_\_\_  
Perforation Interval (3): \_\_\_\_\_  
Tubing: 2 3/8" 4.7# J-55 tbg @ 7165' Rods: \_\_\_\_\_  
Pump: \_\_\_\_\_  
Misc.: \_\_\_\_\_

**PRODUCTION STATUS:** \_\_\_\_\_  
**COMMENTS:** \_\_\_\_\_

### PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 2 3/8" tbg and lay down.
- 3) RU WL. RIH w/ CIBP. Set CIBP @ 7142', dump bail 2 sx of cement on top.
- 4) Unland casing. Cut casing off @ 2500'. POOH with casing laying down on trailer.
- 5) RIH w/ workstring to pump 125 sx stub plug where csg was pulled. If maintain circulation, no need to tag plug.
- 6) POOH w/ workstring to 520'. Pump 200 sx shoe plug. Cement to surface.
- 7) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 8) Cut surface casing off 6'-8' below ground.
- 9) Clean up location. Reclaim location. RDMO.