

WORKOVER PROCEDURE

WELL NAME:	STATE A36-07		DATE:	2/5/2015			
LOCATION:							
Qtr/Qtr:	SWNE	Section:	36	Township:	6N	Range:	64W
Footages:	1790	FNL	&	1991	FEL		
COUNTY:	WELD		STATE:	CO		API #:	05-123-14741
ENGINEER:	DARYL KVEDER			7 Day Notice Sent:			
	(Please notify Engineer of any major changes prior to work)			Do not start operations until:			
				Notice Expires:			
OBJECTIVE:	P&A						
WELL DATA:							
Surface Csg:	8 5/8" 24# @ 317'			KB Elevation:		4637'	
Surface Cmt:	280 sx			GL Elevation:		4627'	
Long St Csg:	2 7/8" 6.5# @ 6936'			TD:		6938'	
Long St Cmt:	275 sx			PBTD:		6885'	
Long St Date:	9/20/1990						
Plug Back (Sand or CIBP):							
Perforation Interval (1):	Codell Perforations 6779' - 6789'						
Perforation Interval (2):							
Perforation Interval (3):							
Tubing:	1 2/3" 2.3# J-55 tbgr @ 6750'			Rods:			
Pump:							
Misc.:							
PRODUCTION STATUS:							
COMMENTS:							

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 1 2/3" tbgr and lay down.
- 3) RU WL. RIH w/ CIBP. Set CIBP @ 6729', dump bail 2 sx of cement on top.
- 4) Unland casing. Cut casing off @ 2500'. POOH with casing laying down on trailer.
- 5) RIH w/ workstring to pump 125 sx stub plug where csg was pulled. If maintain circulation, no need to tag plug.
- 6) POOH w/ workstring to 500'. Pump 200 sx shoe plug. Cement to surface.
- 7) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 8) Cut surface casing off 6'-8' below ground.
- 9) Clean up location. Reclaim location. RDMO.