

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

400787633

Date Received:

02/06/2015

Spill report taken by:

ALLISON, RICK

Spill/Release Point ID:

439283

SPILL/RELEASE REPORT (SUPPLEMENTAL)

This form is to be submitted by the party responsible for the oil and gas spill or release. Any spill or release which may impact waters of the State must be reported as soon as practicable; any spill over 20 bbls must be reported within 24 hours and all spills over five bbls must be reported within ten days. Submit a Site Investigation and Remediation Workplan (Form 27) when requested by the Director.

OPERATOR INFORMATION

Name of Operator: BARRETT CORPORATION\* BILL Operator No: 10071 Address: 1099 18TH ST STE 2300 City: DENVER State: CO Zip: 80202 Contact Person: Rusty Frishmuth Phone Numbers: Phone: (303) 312-8718 Mobile: ( ) Email: rfrishmuth@billbarrettcorp.com

INITIAL SPILL/RELEASE REPORT

Initial Spill/Release Report Doc# 400705099

Initial Report Date: 10/09/2014 Date of Discovery: 10/08/2014 Spill Type: Recent Spill

Spill/Release Point Location:

Location of Spill/Release: QTRQTR NENW SEC 9 TWP 6N RNG 66W MERIDIAN 6

Latitude: 40.507750 Longitude: -104.785531

Municipality (if within municipal boundaries): County: WELD

Reference Location:

Facility Type: TANK BATTERY Facility/Location ID No 433753 No Existing Facility or Location ID No. Well API No. (Only if the reference facility is well) 05-

Fluid(s) Spilled/Released (please answer Yes/No):

Was one (1) barrel or more spilled outside of berms or secondary containment? Yes Secondary containment, including walls & floor regardless of construction material, must be sufficiently impervious to contain any discharge from primary containment until cleanup occurs. Were Five (5) barrels or more spilled? Yes

Estimated Total Spill Volume: use same ranges as others for values

Estimated Oil Spill Volume(bbl): >=5 and <100 Estimated Condensate Spill Volume(bbl): 0 Estimated Flow Back Fluid Spill Volume(bbl): 0 Estimated Produced Water Spill Volume(bbl): 0 Estimated Other E&P Waste Spill Volume(bbl): 0 Estimated Drilling Fluid Spill Volume(bbl): 0

Specify:

Land Use:

Current Land Use: NON-CROP LAND Other(Specify): Weather Condition: Clear, mid 50's, wind out of N Surface Owner: FEE Other(Specify): Land owned by Bill Barrett Corporation

Check if impacted or threatened by spill/Release (please answer Yes/No to all that apply):

Waters of the State Residence/Occupied Structure Livestock Public Byway Surface Water Supply Area As defined in COGCC 100-Series Rules

Describe what is known about the spill/release event (what happened -- including how it was stopped, contained, and recovered):

Dump valves on separators stuck open, caused heater treater to fill with oil, oil was released in a mist through a pressure relief valve on top of the heater treater. Approximately 10 bbls of oil were released. Prevailing winds out of the north carried the mist to the south. An area approximately 50' wide by 100' long was impacted. Impacted soils were scraped up and hauled to Waste Management's Ault landfill for disposal. Confirmation sampling scheduled for 10/14/14.

**List Agencies and Other Parties Notified:**

**OTHER NOTIFICATIONS**

Date	Agency/Party	Contact	Phone	Response
10/9/2014	Weld County OEM	Roy Rudisill	-	via e-mail
10/9/2014	Landowner	Rusty Frishmuth	-	Bill Barrett Corporation is the landowner

**CORRECTIVE ACTIONS**

#1 Supplemental Report Date: 02/06/2015

Cause of Spill (Check all that apply)  Human Error  Equipment Failure  Historical-Unknown  
 Other (specify) \_\_\_\_\_

Describe Incident & Root Cause (include specific equipment and point of failure)

Dump valves on separators stuck open, caused heater treater to fill with oil, oil was released in a mist through a pressure relief valve on top of heater treater. Approximately 10 bbls of oil were released. Prevailing winds out of the north carried the mist to the south. An area approximately 50' wide by 100' long was impacted. Impacted soils were scraped up and hauled to Waste mangements's Ault landfill for disposal. Confirmation sampling was conducting following the initial round of soil removal. Results indicated additional removal was necessary. Following the second round of soil removal, confirmation soil samples indicated compliance with Table 910.

Describe measures taken to prevent the problem(s) from reoccurring:

The dump valves were replaced on the separators.

Volume of Soil Excavated (cubic yards): 148

Disposition of Excavated Soil (attach documentation)  Offsite Disposal  Onsite Treatment  
 Other (specify) \_\_\_\_\_

Volume of Impacted Ground Water Removed (bbls): 0

Volume of Impacted Surface Water Removed (bbls): 0

**REQUEST FOR CLOSURE**

**Spill/Release Reports should be closed when impacts have been remediated or when further investigation and corrective actions will take place under an approved Form 27.**

Basis for Closure:  Corrective Actions Completed (documentation attached)

Work proceeding under an approved Form 27

Form 27 Remediation Project No: \_\_\_\_\_

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: \_\_\_\_\_ Print Name: Rusty Frishmuth

Title: Env Mgr Date: 02/06/2015 Email: rfrishmuth@billbarrettcorp.com

**Attachment Check List**

<u>Att Doc Num</u>	<u>Name</u>
400787663	DISPOSAL MANIFEST
400787664	DISPOSAL MANIFEST
400787665	ANALYTICAL RESULTS

Total Attach: 3 Files

**General Comments**

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>

Total: 0 comment(s)