

WORKOVER PROCEDURE

WELL NAME: State A34-14 **DATE:** 2/11/2015
LOCATION:
Qtr/Qtr: SE/SW Section: 36 Township: 6N Range: 64W
Footages: 630 FSL: 1980 FWL: _____
COUNTY: WELD **STATE:** CO **API #:** 05-123-14792

ENGINEER: DARYL KVEDER 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8-5/8" 24# @ 317' KB Elevation: 4633'
Surface Cmt: Surface to 317' sx GL Elevation: 4643
Long St Csg: 2-7/8" 6.5# @ 6912' TD: 6925'
Long St Cmt: 290 sx PBTD: 6892'
Long St Date: 10/29/1990

Plug Back (Sand or CIBP): _____
Perforation Interval (1): Codell Perforations 6771-6782'
Perforation Interval (2): _____
Perforation Interval (3): _____
Tubing: 1.66" 2.33# N-80 @ 6747.56' Rods: _____
Pump: _____
Misc.: _____

PRODUCTION STATUS: _____
COMMENTS: _____

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 2 3/8" tbg and lay down.
- 3) RU WL. RIH w/ CIBP. Set CIBP @ 6721', dump bail 2 sx of cement on top.
- 4) Unland casing. Cut casing off @ 2500'. POOH with casing laying down on trailer.
- 5) RIH w/ workstring to pump 125 sx stub plug where csg was pulled. If maintain circulation, no need to tag plug.
- 6) POOH w/ workstring to 655'. Pump 235 sx shoe plug. Cement to surface.
- 7) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 8) Cut surface casing off 6'-8' below ground.
- 9) Clean up location. Reclaim location. RDMO.