

WORKOVER PROCEDURE

WELL NAME: MELVIN Y04-04 **DATE:** 2/20/2015
LOCATION:
Qtr/Qtr: NWNW Section: 4 Township: 2N Range: 64W
Footages: 990 FNL & 990 FWL
COUNTY: WELD **STATE:** CO **API #:** 05-123-16972

ENGINEER: JANELLE SHABLE 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8" 24# @ 825' KB Elevation: 4884
Surface Cmt: 575 sx GL Elevation: 4874
Long St Csg: 4 1/2" 11.6# @ 7685' TD: 7685
Long St Cmt: 360 sx + 330 sx PBDT: 7633
Long St Date: 6/18/1993

Plug Back (Sand or CIBP): _____
Perforation Interval (1): Sussex Perforations 4514' - 4534'
Perforation Interval (2): Niobrara Perforations 6850' - 6856'
Perforation Interval (3): Codell Perforations 7076' - 7086'
Perforation Interval (4): Jsand Perforations 7537' - 7580'
Tubing: 2 3/8" J-55 tbg @ 7515' Rods: _____
Pump: _____
Misc.: _____

PRODUCTION STATUS: _____
COMMENTS: _____

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 2 3/8" tbg and lay down.
- 3) RU WL. RIH w/ CIBP. Set CIBP @ 7487', dump bail 2 sx of cement on top.
- 4) RIH w/ CIBP. Set CIBP @ 6800', dump bail 2 sx of cement on top.
- 5) RIH w/ CIBP. Set CIBP @ 4464', dump bail 2 sx of cement on top.
- 6) Unland casing. Cut casing off @ 2500'. POOH with casing laying down on trailer.
- 7) RIH w/ workstring to pump 100 sx stub/shoe plug where csg was pulled. If maintain circulation, no need to tag plug.
- 8) POOH w/ workstring to 925'. Pump 350 sx shoe plug. Cement to surface.
- 9) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 10) Cut surface casing off 6'-8' below ground.
- 11) Clean up location. Reclaim location. RDMO.