

WORKOVER PROCEDURE

WELL NAME: SCHOLFIELD STATE A36-04X **DATE:** 3/17/2015
LOCATION:
Qtr/Qtr: NW/NW Section: 36 Township: 6N Range: 64W
Footages: 535 FNL: & 535 FWL
COUNTY: WELD **STATE:** CO **API #:** 05-123-30044

ENGINEER: DARYL KVEDER 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8-5/8" 24# J-55 @ 438' KB Elevation: 4642
Surface Cmt: 224 sx GL Elevation: 4629
Long St Csg: 4-1/2" 11.6# M-80 @ 7034' TD: 7048
Long St Cmt: 840 sx PBTD: 6990
Long St Date: 6/3/2009

Plug Back (Sand or CIBP): _____
Perforation Interval (1): Niobrara Perforations (6594-6606, 6707-6719)
Perforation Interval (2): Codell Perforations (6870-6884)
Perforation Interval (3): _____
Tubing: 2-3/8" 4.7# J-55 @6858' Rods: _____
Pump: _____
Misc.: _____

PRODUCTION STATUS: _____
COMMENTS: _____

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 2 3/8" tbg and lay down.
- 3) RU WL. RIH w/ CIBP. Set CIBP @ 6544', dump bail 2 sx of cement on top.
- 4) RIH w/ workstring to 2500'. Pump 20 sx courtesy plug.
- 5) With casing in slips. Cut casing @ 600'. POOH with casing laying down on trailer.
- 6) RIH w/ workstring to 600'. Pump 200 sx shoe plug. Cement to surface.
- 7) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 8) Cut surface casing off 6'-8' below ground.
- 9) Clean up location. Reclaim location. RDMO.