

# REENTRY PROCEDURE

WELL NAME: UPRR 36 PAN AM B 1 DATE: 9/17/2014  
 LOCATION: Qtr/Qtr: SWSW Section: 17 Township: 4N Range: 64W  
 COUNTY: WELD STATE: CO API #: 05-123-07280

ENGINEER: Ryan Olson 7 Day Notice Sent: \_\_\_\_\_  
 (Please notify Engineer of any major Do not start operations until: \_\_\_\_\_  
 changes prior to work) Notice Expires: \_\_\_\_\_

OBJECTIVE: Re-enter and re-plug

WELL DATA: Surface Csg: 8 5/8" 24# set @ 406' KB Elevation: 4754'  
 Surface Cmt: 400 sks GL Elevation: 4744'  
 Long St Csg: NO PROD CSG TD: 7580'  
 Long St Cmt: \_\_\_\_\_ PBTD: \_\_\_\_\_  
 Long St Date: \_\_\_\_\_  
 Plug Info (1) 25 sk cmt plug set from 7340'-7430'  
 Plug Info (2) 30 sk cmt plug set from 330'-400'  
 Plug Info (3) 10 sk cmt plug set @ surface  
 Plug Info (4) \_\_\_\_\_  
 Tubing: \_\_\_\_\_ Rods: \_\_\_\_\_  
 Pump: \_\_\_\_\_  
 Misc.: Base Fox Hills @ 410', Deepest water well @ 420'

WELL STATUS: Well abandoned 4/3/71

COMMENTS: \_\_\_\_\_  
 \_\_\_\_\_

## PROCEDURE:

- 1) Survey and locate abandoned well, mark with stake
- 2) Excavate to expose top of surface casing
- 3) Weld 2" collar to top of 8 5/8" surface casing cap. Make up to collar, pneumatic drill with non-sparking bit. Drill out cap venting possible trapped gas.
- 4) Once verified that no gas exists beneath top of surface casing plate, cut off surface casing below plate with torch, dress up smooth.
- 5) Butt weld 8 5/8" casing to dressed cut, bringing threaded end of casing to ground level.
- 6) Make up to 8 5/8" casing, one 8 5/8" collar and 8 5/8" starter well head
- 7) NU flange adaptor and 5k BOP, test BOP.
- 8) NU and RIH with 6 7/8" cone bit, PU 2 7/8" drill collar, 2 7/8" 8.7# tubing, and TIW valve
- 9) Drill out first cement plug inside surface casing, roll hole clean. Verify top of next cement plug inside of surface casing by tagging (assumption).
- 10) If unable to verify isolation of surface casing with tag of cement plug, set RBP inside surface casing
- 11) Once isolation of surface casing is established, either with tagging of surface plug or setting of RBP, pressure test surface casing to 200psi
- 12) After pressure test of surface casing, retrieve RBP or continue drill out of cement plug under surface casing shoe.
- 13) Assume pressure under surface casing shoe, roll hole with kill fluid until well dead, or blow down.
- 14) Continue RIH, cleaning out with drilling mud or water to 3000'
- 15) TOOH with cone bit, drill collars, and 2 7/8" tubing.
- 16) PU and RIH with mule shoe and 2 7/8" tubing to 3000'
- 17) RU cement crew and pump a balanced plug of 100 sks 15.8 ppg Class G "neat" cement
- 18) POOH to 560' (150' below Fox Hills base @ 410')
- 19) RU cement crew and pump 235 sxs of 15.8ppg Class G "neat" cement bring cement to surface
- 20) POOH with 2 7/8" tubing. Wait 4 hrs, and tag TOC. If cement has fallen, top off back to surface
- 21) Let cement set over night, verify cement has not settled and is still at surface. RDMO