

WORKOVER PROCEDURE

WELL NAME: STATE SLW 18-24 **DATE:** 4/20/2015

LOCATION:
Qtr/Qtr: SE/NW Section: 18 Township: 5N Range: 63W
Footages: 1922' FNL & 1962' FWL

COUNTY: WELD **STATE:** CO **API #:** 05-123-22665

ENGINEER: Jonathan Pomerantz 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA:

Surface Csg:	8 5/8" 24# @ 395'	KB Elevation:	4606'
Surface Cmt:	175 sx	GL Elevation:	4596'
Long St Csg:	4 1/2" 11.6# @ 6802'	TD:	6811'
Long St Cmt:	147 sx	PBTD:	6661'
Long St Date:	2/8/2005		

Plug Back (Sand or CIBP): _____
Perforation Interval (1): Niobrara Perforations 6484' - 6560'
Perforation Interval (2): Codell Perforations 6642' - 6654'
Perforation Interval (3): _____
Tubing: 2 3/8" 4.7# J-55 tbg @ 6627' Rods: _____
Pump: _____
Misc.: _____

PRODUCTION STATUS: _____
COMMENTS: _____

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 2 3/8" tbg and lay down.
- 3) RU WL. RIH w/ CIBP. Set CIBP @ 6434', dump bail 2 sx of cement on top.
- 4) Unland casing. Cut casing off @ 2500'. POOH w/ casing laying down on trailer.
- 5) RIH w/ workstring to pump 100 sx stub plug where csg was pulled. If maintain circulation, no need to tag plug.
- 6) POOH w/ workstring to 500'. Pump 200 sx shoe plug. Cement to surface.
- 7) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 8) Cut surface casing off 6'-8' below ground.
- 9) Clean up location. Reclaim location. RDMO.