

WORKOVER PROCEDURE

WELL NAME: ACHZIGER B05-09 **DATE:** 5/6/2015
LOCATION:
Qtr/Qtr: NE/SE Section: 5 Township: 5N Range: 64W
Footages: 1980' FSL & 660' FEL
COUNTY: WELD **STATE:** CO **API #:** 05-123-13827

ENGINEER: Jonathan Pomerantz 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8" 24# @ 292' KB Elevation: 4631'
Surface Cmt: 305 sx GL Elevation: 4620'
Long St Csg: 4 1/2" 15.1# @ 7005' TD: 7018'
Long St Cmt: 220 sx PBTD: 6903'
Long St Date: 2/22/1988

Plug Back (Sand or CIBP): _____
Perforation Interval (1): Niobrara Perforations 6559' - 6767'
Perforation Interval (2): Codell Perforations 6851' - 6891'
Perforation Interval (3): _____
Tubing: 2 3/8" 4.7# J-55 @ 6834' Rods: _____
Pump: _____
Misc.: _____

PRODUCTION STATUS: _____
COMMENTS: _____

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 2 3/8" tbg and lay down.
- 3) RU WL. RIH w/ CIBP. Set CIBP @ 6509', dump bail 2 sx of cement on top.
- 4) Unland casing. Cut casing off @ 2500'. POOH w/ casing laying down on trailer.
- 5) RIH w/ workstring to pump 100 sx stub plug where csg was pulled. If maintain circulation, no need to tag plug.
- 6) POOH w/ workstring to 430'. Pump 175 sx shoe plug. Cement to surface.
- 7) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 8) Cut surface casing off 6'-8' below ground.
- 9) Clean up location. Reclaim location. RDMO.