

WORKOVER PROCEDURE

WELL NAME: Lilli Unit 10-7 **DATE:** 5/27/2015
LOCATION: Qtr/Qtr: NW/SE Section: 7 Township: 8N Range: 58W
Footages: 2120' FSL & 2120 FEL
COUNTY: WELD **STATE:** CO **API #:** 05-123-13873

ENGINEER: Ben Zapp PE 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8" 24# @ 185' KB Elevation: 4,801.00
Surface Cmt: 115 sx GL Elevation: 4,791.00
Long St Csg: 5 1/2" 15.5# @ 6,640' TD: 6,640.00
Long St Cmt: 140 sx PBTD: 6,580.00
Long St Date: 3/18/1988

Plug Back (Sand or CIBP): Tag
Perforation Interval (1): D Sand 6,499' - 6,502'
Perforation Interval (2): _____
Perforation Interval (3): _____
Tubing: 1 1/2" @ 6,538' Rods: NA
Pump: NA
Misc.: _____

PRODUCTION STATUS: SI
COMMENTS: TOC @ 6,270' is below Nio top @ 5,740'

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 1 1/2" tbg and lay down.
- 3) RU WL. RIH w/ CIBP. Set CIBP @ 6,448', dump bail 2 sx of cement on top.
- 4) Unland casing. Cut casing off @ 5,790'. POOH with casing laying down on trailer. Nio top @ 5,740'
- 5) RIH w/ workstring to pump 110 sx stub plug where csg was pulled. If maintain circulation, no need to tag plug.
- 6) RIH w/ workstring to pump 50 sx courtesy plug @ 2,500'. If maintain circulation, no need to tag plug.
- 7) POOH w/ workstring to 285'. Pump 130sx shoe plug. Cement to surface.
- 8) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 9) Cut surface casing off 6'-8' below ground.
- 10) Clean up location. Reclaim location. RDMO.