



## Exploration and Production Well P&A Procedure

Wellname **GM 238-36**  
Location **SWSE 36 6S 96W**  
Field **Grand Valley**  
County **Garfield, CO**  
API **05-045-07918**  
ELEV **5,442'**  
Footages **828 FSL, 2428 FEL**

Prepared By: Tony Franzone  
office phone: 970-285-9377  
cell phone: 970-589-1454

Revision Date:  
6/3/2015

Casing: 9-5/8" 32.3#, H-40 - 758-ft  
4-1/2" 11.6#, I-80 - 6,812-ft  
Current Top of Cement: 4,200-ft CBL (HAL 05/12/02)

**Purpose: Plug to abandon well**

Zone: **All Perforations**

Existing Perforations:	Depth	Holes
	5089 - 5354	18
	5573 - 5820	16
	5922 - 6225	16
	6360 - 6618	20
		<hr/>
		70 total

### Proposed Procedure

- 1 Notify COGCC 48 hrs prior to start of activity via electronic Form 42
- 2 Set CIBP + 2 sks cement at 5040' ft in 4-1/2" casing
- 3 Pressure test 4-1/2" casing, pump cement into leaking area, if necessary
- 4 Set CIBP at 860' in 4-1/2" casing, perforate 4-1/2" casing with 3 holes phased 120°, at 810'
- 5 Place a cement plug to cover 4-1/2" backside from perforations to 50' into 9-5/8", and leaving 100' cement in 4-1/2", with a 30% open hole cement excess
- 6 Cut off 9-5/8" and 4-1/2" casing to 4-ft below ground level
- 7 Apply a 50-ft cement plug from surface in 4-1/2" - 9-5/8" annulus
- 8 Place a 50-ft surface cement plug inside 4-1/2" casing
- 9 Weld in place dryhole marker
- 10 Backfill cellar
- 11 Properly abandon flowlines per Rule 1103. File electronic Form 42 after flowline abandonment is complete