

WORKOVER PROCEDURE

WELL NAME: Rydgren 08-01 **DATE:** 6/30/2015
LOCATION:
Qtr/Qtr: NW/SE Section: 8 Township: 4N Range: 64W
Footages: 1980' FSL & 660' FWL
COUNTY: WELD **STATE:** CO **API #:** 05-123-11897

ENGINEER: Hilary Ramseier 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8-5/8" 24# J-55 @ 402' KB Elevation: 4,828'
Surface Cmt: 165 sx GL Elevation: 4,816'
Long St Csg: 4-1/2" 11.6# @ 7,135' TD: 7,141'
Long St Cmt: 190 sx PBTD: 7,015'
Long St Date: 7/23/1984

Plug Back (Sand or CIBP): _____
Perforation Interval (1): Codell Perforations 7,024 - 7,038
Perforation Interval (2): _____
Perforation Interval (3): _____
Tubing: 2-3/8" 4.7# J-55 @ 7,010' Rods: _____
Pump: _____
Misc.: _____

PRODUCTION STATUS: Currently producing 0 bopd and 0 mcfd due to having a 250 psi rated separator w/ 250+ psi line
COMMENTS: pressure. Pressures 595/595

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 2 3/8" tbg and lay down.
- 3) RU WL. RIH w/ CIBP. Set CIBP @ 6,974'. ROOH.
- 4) RIH w/ workstring. Pump 27 sx cement on top of CIBP. (must cover 100' above Nio)
- 5) Unland casing. Cut casing off @ 2500'. POOH with casing laying down on trailer.
- 7) RIH w/ workstring to pump 100 sx stub plug where csg was pulled. If maintain circulation, no need to tag plug.
- 8) POOH w/ workstring to 530'. Pump 205 sx shoe plug. Cement to surface.
- 9) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 10) Cut surface casing off 6'-8' below ground.
- 11) Clean up location. Reclaim location. RDMO.