

WORKOVER PROCEDURE

WELL NAME: NIKOLORIC C05-05 **DATE:** 7/8/2015

LOCATION: Qtr/Qtr: SW/NW Section: 5 Township: 4N Range: 64W

Footages: 1943' FNL & 649' FWL

COUNTY: WELD **STATE:** CO **API #:** 05-123-20235

ENGINEER: Jonathan Pomerantz 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8" 24# @ 490' KB Elevation: 4763'
Surface Cmt: 345 sx GL Elevation: 4753'
Long St Csg: 4 1/2" 11.6# @ 7600' TD: 7606'
Long St Cmt: 250 sx PBTD: 7583'
Long St Date: 8/31/2001

Plug Back (Sand or CIBP): _____
Perforation Interval (1): J-Sand Perforations 7442' - 7502'
Perforation Interval (2): _____
Perforation Interval (3): _____
Tubing: 2 3/8" 4.7# J-55 tbg @ 7435' Rods: _____
Pump: _____
Misc.: _____

PRODUCTION STATUS: _____

COMMENTS: _____

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 2 3/8" tbg and lay down.
- 3) RU WL. RIH w/ CIBP. Set CIBP @ 7392', dump bail 2 sx of cement on top.
- 4) RIH w/ workstring to 6900'. Pump 30 sx balance plug. If maintain circulation, no need to tag plug.
- 5) Unland casing. Cut casing off @ 2500'. POOH w/ casing laying down on trailer.
- 6) RIH w/ workstring to pump 100 sx stub plug where csg was pulled. If maintain circulation, no need to tag plug.
- 7) POOH w/ workstring to 600'. Pump 225 sx shoe plug. Cement to surface.
- 8) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 9) Cut surface casing off 6'-8' below ground.
- 10) Clean up location. Reclaim location. RDMO.