



Plugging Procedure

Well Name: Mary Mills 41-18

API 05123127820000	Surface Legal Location NENE 18 4N 64W	Field Name Wattenberg	State CO	Well Configuration Type Vertical
Ground Elevation (ft) 4,800.00	Original KB Elevation (ft) 4,812.00	KB-Ground Distance (ft) 12.00	Spud Date 11/2/1985 00:00	Rig Release Date On Production Date 1/8/1986

Task Details

Type Well Abandonment	Sub Type Proposed Plugging Procedure	Completed Date
--------------------------	---	----------------

Action Details

Proposed Plugging Procedure

Surface Csg: 8-5/8" - 24# - Set @ 335' w/ 180 sxs to surface.
Production Csg: 4-1/2" - 11.6# - Set @ 7,169' w/ 200 sxs.
CBL TOC @ 6,275' (CBL needed)

- 1) MIRU WO rig. Make sure well is dead.
- 2) POOH w/ any tubing in hole.
- 3) MIRU WL unit.
- 4) PU CBL assey.
- 5) RIH and log entire well.
- 4) Locate TOC. (If major changes, adjust cut depth and contact engineer and state for approval.)
- 6) RD WL unit.
- 7) RU cmt services.
- 8) RU WL.
- 9) PU CIBP.
- 10) RIH w/ CIBP and set @ 6,974'.
- 11) POOH w/ WL.
- 12) PU dump bailer w/ 2 sxs of cmt.
- 13) RIH w/ bailer and spot cmt on CIBP from 6,973' to 6,945'.
- 15) POOH.
- 16) PU casing cutter tool.
- 17) RIH w/ cutter and cut 4.5" production csg @ 6,150'.
- 18) POOH w/ cutter.
- 19) RD WL.
- 20) POOH w/ cut section of csg and lay down.
- 21) PU work sting.
- 22) RIH and spot a 50 sx balance plug from 6,200' to 5,986' @ csg stub.
- 23) TOOH and spot a 338 sx balance plug from 4,912' to 3,714' (Covering Sussex/Parkman).
- 24) TOOH and spot a 279 sx balance plug from 1,000' to surface.
- 25) WOC.
- 26) Top off any remaining volume.
- 27) RDMO service units.
- 28) Cut and weld cap.