

Hill 11-6 plugging procedure

Whiting intends to P&A the referenced well as follows:

1. Pull production equipment.
2. Set a CICR @ 6100'.
3. Squeeze 55 sx cement below CICR @ 6100' and leave 10 sx cement above CICR.
4. Pressure test casing to 300#.
5. Balance a 25 sk cement plug with EOT @ 4400'.
6. Shoot squeeze holes @ 1600'.
7. Set a CICR @ 1500'.
8. Squeeze 50 sx cement below CICR @ 1500' and leave 10 sx cement above CICR.
9. Shoot squeeze holes @ 400'.
10. Circulate cement (~120 sx) inside and outside 5-1/2" casing from 400' to surface.
11. Cut off wellhead & install identification marker.
12. Reclaim surface location.

Notes:

Plugging will be executed per regulations.

Mud spacers of 9 ppg or greater will be placed between cement plugs.