

WORKOVER PROCEDURE

WELL NAME: Lilli Unit 10-01 **DATE:** 9/18/2015
LOCATION:
Qtr/Qtr: NWSE Section: 1 Township: 8N Range: 59W
Footages: 1780' FSL & 1780' FEL
COUNTY: WELD **STATE:** CO **API #:** 05-123-14012

ENGINEER: Ben Zapp PE 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8" 24# @ 263' KB Elevation: 4,823.00
Surface Cmt: 170 sx GL Elevation: 4,814.00
Long St Csg: 4 1/2" 10.5# @ 6642' TD: 6,642.00
Long St Cmt: 190 sx PBTD: 6,589.00
Long St Date: 8/5/1988

Plug Back (Sand or CIBP): Tag
Perforation Interval (1): D Sand 6,530' - 6,550'
Perforation Interval (2): _____
Perforation Interval (3): _____
Tubing: 2 3/8" @ 6572' Rods: Yes
Pump: Yes
Misc.: _____

PRODUCTION STATUS: TA @ 6378'
COMMENTS: _____

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ rods, pump & 2-3/8" tbg and lay down.
- 3) RU WL. RIH w/ CIBP. Set CIBP @ 6,480', dump bail 2 sx of cement on top.
- 4) RIH and pump 10sxs over Nio top at 5,780'
- 5) Unland casing. Cut casing off @ 2,500'. POOH with casing laying down on trailer.
- 6) RIH w/ workstring to pump 100 sx stub plug where csg was pulled. If maintain circulation, no need to tag plug.
- 7) POOH w/ workstring to 440'. Pump 265 sx shoe plug. Cement to surface. (Water well at 290')
- 8) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 9) Cut surface casing off 6'-8' below ground.
- 10) Clean up location. Reclaim location. RDMO.