

WORKOVER PROCEDURE

WELL NAME: Dechant Farms 16-36 **DATE:** 10/9/2015

LOCATION: Qtr/Qtr: SE/SE Section: 36 Township: 3N Range: 65W

Footages: 660' FSL & 860' Township: 3N Range: 65W
660' FSL & 860' FEL

COUNTY: WELD **STATE:** CO **API #:** 05-123-19101

ENGINEER: Benjamin Daniell 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8-5/8" 24# @ 663' KB Elevation: 4833'
Surface Cmt: 465 sx GL Elevation: 4823'
Long St Csg: 4-1/2" 11.6# I-70 @ 7217' TD: 7226'
Long St Cmt: 240 sx PBTD: 7151'
Long St Date: 3/16/1996

Plug Back (Sand or CIBP): _____
Perforation Interval (1): Sussex Perforations 4480' - 4485'
Perforation Interval (2): Niobrara Perforations 6845' - 6846'
Perforation Interval (3): Codell Perforations 7072' - 7082'
Tubing: 2-3/8" 4.7# J-55 @ 7041' Rods: NA
Pump: NA
Misc.: _____

PRODUCTION STATUS: _____

COMMENTS: _____

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 2 3/8" tbg and lay down.
- 3) RU WL. RIH w/ CIBP. Set CIBP @ 6795', dump bail 2 sx of cement on top.
- 4) RIH w/ CIBP. Set CIBP @ 4430', dump bail 2 sx of cement on top.
- 5) Unland casing. Cut casing off @ 2500'. POOH with casing laying down on trailer.
- 6) RIH w/ workstring to pump 125 sx stub plug where csg was pulled. If maintain circulation, no need to tag plug.
- 7) POOH w/ workstring to 805'. Pump 265 sx shoe plug. Cement to surface.
- 8) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 9) Cut surface casing off 6'-8' below ground.
- 10) Clean up location. Reclaim location. RDMO.