

WORKOVER PROCEDURE

WELL NAME:	UPRC 7-09G		DATE:	10/12/2015			
LOCATION:							
Qtr/Qtr:	NESE	Section:	7	Township:	4N	Range:	65W
Footages:	1980	FSL	&	660	FWL		
COUNTY:	WELD		STATE:	CO		API #:	05-123-15174
ENGINEER:	AJ Paine		7 Day Notice Sent:				
	(Please notify Engineer of any major changes prior to work)		Do not start operations until:				
			Notice Expires:				
OBJECTIVE:	P&A						
WELL DATA:							
Surface Csg:	8 5/8", 23# @ 503'				KB Elevation:	4707'	
Surface Cmt:	350 sx				GL Elevation:	4698'	
Long St Csg:	4 1/2", 11.6#, M-75 @ 7270'				TD:	7277'	
Long St Cmt:	200 & 200 sx				PBTD:	7215'	
Long St Date:	9/21/1991						
Plug Back (Sand or CIBP):	Sand						
Perforation Interval (1):	Niobrara Perforations: 6847' - 7043'						
Perforation Interval (2):	Codell Perforations: 7149' - 7164'						
Perforation Interval (3):							
Tubing:	2 3/8", 4.7#, J-55 @ 7132'				Rods:		
Pump:							
Misc.:							
PRODUCTION STATUS:	Producing 0.5 bopd and 20 mcf/d. Pressures @ 270/270						
COMMENTS:	Can't payout WBI/STEM costs						

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH and lay down 2 3/8" tubing.
- 3) RU WL. RIH w/ CIBP. Set CIBP @ 6797', dump bail 2 sx cement on top.
- 4) RIH w/ workstring to pump 30 sx balance plug from 4300' - 3920'.
- 5) Unland casing. Cut 4 1/2" casing @ 2500'. POOH and laydown casing.
- 6) RIH w/ workstring to pump 100 sx stub plug where casing was pulled. If maintain circulation, no need to tag plug.
- 7) POOH w/ workstring to 603'. Pump 205 sx shoe plug. Cement to surface.
- 8) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 9) Cut surface casing off 6'-8' below ground.
- 10) Clean up location. Reclaim location. RDMO.