

WORKOVER PROCEDURE

WELL NAME: STATE HOPPE 16-03 **DATE:** 1/12/2016

LOCATION: Qtr/Qtr: SW/NW Section: 16 Township: 6N Range: 66W

Footages: 2157 FNL & 664 FWL

COUNTY: WELD **STATE:** CO **API #:** 05-123-12521

ENGINEER: JOHN HATCH 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8" 24# @306' KB Elevation: 4789'
Surface Cmt: 210 sx GL Elevation: 4782'
Long St Csg: 4 1/2" 11.60#, N-80 @7287' TD: 7330'
Long St Cmt: 150 sx PBDT: 7242'
Long St Date: 7/20/1985

Plug Back (Sand or CIBP): _____
Perforation Interval (1): Niobrara Perforations 6876' - 7104'
Perforation Interval (2): Codell Perforations 7190' - 7204'
Perforation Interval (3): _____
Tubing: No tubing D/H Rods: _____
Pump: _____
Misc.: _____

PRODUCTION STATUS: _____

COMMENTS: _____

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) RU WL. RIH w/ CIBP. Set CIBP @ 6826', dump bail 2 sx of cement on top.
- 3) Unland casing. Cut casing off @ 2500'. POOH with casing laying down on trailer.
- 4) RIH w/ workstring to pump 100 sx stub plug where csg was pulled. If maintain circulation, no need to tag plug.
- 5) POOH w/ workstring to 825'. Pump 340 sx shoe plug. Cement to surface.
- 6) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 7) Cut surface casing off 6'-8' below ground.
- 8) Clean up location. RDMOL.