

## WORKOVER PROCEDURE

**WELL NAME:** AGRICULTURAL PRODUCTS FEDERAL 32-07F **DATE:** 1/14/2016  
**LOCATION:**  
Qtr/Qtr: SW/NE Section: 32 Township: 4N Range: 66W  
Footages: 2153 FNL & 2105 FEL  
**COUNTY:** WELD **STATE:** CO **API #:** 05-123-15577

**ENGINEER:** JOSH CHEBUL 7 Day Notice Sent: \_\_\_\_\_  
(Please notify Engineer of any major Do not start operations until: \_\_\_\_\_  
changes prior to work) Notice Expires: \_\_\_\_\_

**OBJECTIVE:** P&A

**WELL DATA:** Surface Csg: 8-5/8" @ 519' KB Elevation: 4781'  
Surface Cmt: 360 sx GL Elevation: 4770'  
Long St Csg: 4-1/2" 11.6# M-75 @ 7415' TD: 7426'  
Long St Cmt: 200 sx PBTD: 7372'  
Long St Date: 2/26/1992

Plug Back (Sand or CIBP): \_\_\_\_\_  
Perforation Interval (1): Niobrara Perforations 6980'-7000', 7062'-7070', & 7146'-7156'  
Perforation Interval (2): Codell Perforations 7291'-7307'  
Perforation Interval (3): \_\_\_\_\_  
Tubing: 2 3/8" 4.70# J-55 @ 7279' Rods: N/A  
Pump: \_\_\_\_\_  
Misc.: \_\_\_\_\_

**PRODUCTION STATUS:** Producing  
**COMMENTS:** Well is uneconomic to continue to produce.

### PROCEDURE:

- 1) MIRU workover rig, pump & tank.
- 2) POOH w/ 2-3/8" tbg and lay down.
- 3) RU WL. RIH w/ CIBP. Set CIBP @ 6930'. Dump bail 2 sx of cement on top.
- 4) Unland casing. Cut casing off @ 2500'. POOH with casing and lay down on trailer.
- 5) RIH w/ workstring to pump 100 sx stub plug where csg was pulled. If maintain circulation, no need to tag plug.
- 6) POOH w/ workstring to 690'. Pump 215 sx shoe plug. Cement to surface.
- 7) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 8) Cut surface casing off 6'-8' below ground.
- 9) Clean up location. RDMOL.