

## WORKOVER PROCEDURE

**WELL NAME:** Wells Ranch USX BB01-10 **DATE:** 1/19/2016  
**LOCATION:**  
Qtr/Qtr: NW/SE Section: 1 Township: 5N Range: 63W  
Footages: 2059' FSL & 1968' FEL  
**COUNTY:** WELD **STATE:** CO **API #:** 05-123-26131

**ENGINEER:** Benjamin Daniell 7 Day Notice Sent: \_\_\_\_\_  
(Please notify Engineer of any major Do not start operations until: \_\_\_\_\_  
changes prior to work) Notice Expires: \_\_\_\_\_

**OBJECTIVE:** P&A

**WELL DATA:** Surface Csg: 8 5/8" 24# J-55 @ 443' KB Elevation: 4691'  
Surface Cmt: 239 sx GL Elevation: 4679'  
Long St Csg: 4 1/2" 11.6# M-80 @ 6753' TD: 6765'  
Long St Cmt: 910 sx PBTD: 6709'  
Long St Date: 8/10/2007

Plug Back (Sand or CIBP): \_\_\_\_\_  
Perforation Interval (1): Niobrara Perforations 6370' - 6450'  
Perforation Interval (2): Codell Perforations 6606' - 6615'  
Perforation Interval (3): \_\_\_\_\_  
Tubing: 2-3/8" 4.7# J-55 @ 6349' Rods: NA  
Pump: NA  
Misc.: \_\_\_\_\_

**PRODUCTION STATUS:** SI for STEM  
**COMMENTS:** Doesn't cover STEM/WBI work required

### PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 2 3/8" tbg and lay down.
- 3) RU WL. RIH w/ CIBP. Set CIBP @ 6320'; dump bail 2 sx of cement on top.
- 4) RIH w/ workstring to pump 30 sx balance/courtosey plug @ 2500'. If maintain circulation, no need to tag plug.
- 5) Unland casing. Cut casing off @ 1600'. POOH with casing laying down on trailer.
- 6) RIH w/ workstring to pump 100 sx stub plug where csg was pulled. If maintain circulation, no need to tag plug.
- 7) POOH w/ workstring to 543'. Pump 170 sx shoe plug. Cement to surface.
- 8) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 9) Cut surface casing off 6'-8' below ground.
- 10) Clean up location. Reclaim location. RDMO.