

WORKOVER PROCEDURE

WELL NAME: ALLES A12-16 **DATE:** 11/5/2015

LOCATION: Qtr/Qtr: SESE Section: 12 Township: 6N Range: 64W

Footages: _____
&

COUNTY: WELD **STATE:** CO **API #:** 05-123-23276

ENGINEER: JASON LEHMAN 7 Day Notice Sent: _____

(Please notify Engineer of any major Do not start operations until: _____

changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8-5/8" 24# J-55 @ 456' KB Elevation: 4,686'

Surface Cmt: 320 sx GL Elevation: 4,674'

Long St Csg: 4-1/2" 11.6# N-80 @ 6934' TD: 6,960'

Long St Cmt: 610 sx PBTD: 6,906'

Long St Date: 11/25/2005

Plug Back (Sand or CIBP): _____

Perforation Interval (1): Niobrara Perforations: 6,548' - 6,562'; 6,668' - 6,680'

Perforation Interval (2): Codell Perforations: 6,834' - 6,845'

Perforation Interval (3): _____

Tubing: 2-3/8" 4.7# 6,812' Rods: _____

Pump: _____

Misc.: _____

PRODUCTION STATUS: Determined Hole In Casing when swabbing.

COMMENTS: _____

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 2-3/8" tbg and lay down.
- 3) RU WL. RIH w/ CIBP. Set CIBP @ 6498', dump bail 2 sx of cement on top.
- 4) Unland casing. Cut casing off @ 2500'. POOH with casing laying down on trailer.
- 5) RIH w/ workstring to pump 125 sx stub plug where csg was pulled. If maintain circulation, no need to tag plug.
- 6) POOH w/ workstring to 565'. Pump 145 sx shoe plug. Cement to surface.
- 7) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 8) Cut surface casing off 6'-8' below ground.
- 9) Clean up location. Reclaim location. RDMO.