

WORKOVER PROCEDURE

WELL NAME: Larson A25-06X **DATE:** 2/9/2016

LOCATION:

Qtr/Qtr: SENW Section: 25 Township: 6N Range: 64W
Footages: 2105' FNL & 1880' FWL

COUNTY: WELD **STATE:** CO **API #:** 05-123-26586

ENGINEER: NARAYAN CHOUDHARY 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8" 24# @ 773' KB Elevation: 4645'
Surface Cmt: 295 sx GL Elevation: 4632'
Long St Csg: 4 1/2" 11.60# M-80@ 7031' TD: 7052'
Long St Cmt: 910 sx PBTD: 7002'
Long St Date: 11/28/2007

Plug Back (Sand or CIBP): _____
Perforation Interval (1): Niobrara Perforations 6595' - 6724'
Perforation Interval (2): Codell Perforations 6890' - 6902'
Perforation Interval (3): _____
Tubing: 2 3/8" 4.70# J-55 @ 6858' Rods: _____
Pump: _____
Misc.: _____

PRODUCTION STATUS: SI
COMMENTS: UNECONOMIC FOR WBI WORK

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 2 3/8" tbg and lay down.
- 3) RU WL. RIH w/ CIBP. Set CIBP @ 6545', dump bail 2 sx of cement on top.
- 4) Unland casing. Cut casing off @ 1450'. POOH with casing laying down on trailer.
- 5) RIH w/ workstring to pump 100 sx stub plug @ 1450'. If maintain circulation, no need to tag plug.
- 6) POOH w/ workstring to 873'. Pump 271 sx shoe plug. Cement to surface.
- 7) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 8) Cut surface casing off 6'-8' below ground.
- 9) Clean up location. Reclaim location. RDMO.