

WORKOVER PROCEDURE

WELL NAME: TRE-MAT 23-13 **DATE:** 2/23/2016
LOCATION:
Qtr/Qtr: SW/NE Section: 23 Township: 6N Range: 67W
Footages: 2168 FNL & 1958 FEL
COUNTY: WELD **STATE:** CO **API #:** 05-123-23551

ENGINEER: JOHN HATCH 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8" 24# @581' KB Elevation: 4787'
Surface Cmt: 247 sx GL Elevation: 4777'
Long St Csg: 4 1/2" 11.60#, M-80 @ 7327' TD: 7344'
Long St Cmt: 755 sx PBTD: 7300'
Long St Date: 8/2/2006

Plug Back (Sand or CIBP): _____
Perforation Interval (1): Niobrara Perforations 6955' - 6970'
Perforation Interval (2): Codell Perforations 7145' - 7163'
Perforation Interval (3): _____
Tubing: 2 3/8" @7129' Rods: _____
Pump: _____
Misc.: _____

PRODUCTION STATUS: _____
COMMENTS: _____

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 2 3/8" tbg and lay down.
- 3) RU WL. RIH w/ CIBP. Set CIBP @ 6905', dump bail 2 sx of cement on top.
- 4) Unland casing. Cut casing off @ 2500'. POOH with casing laying down on trailer.
- 5) RIH w/ workstring to pump 100 sx stub plug where csg was pulled. If maintain circulation, no need to tag plug.
- 6) POOH w/ workstring to 631'. Pump 229 sx shoe plug. Cement to surface.
- 7) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 8) Cut surface casing off 6'-8' below ground.
- 9) Clean up location. RDMOL.