

WORKOVER PROCEDURE

WELL NAME: DETIENNE 01-23 **DATE:** 2/24/2016
LOCATION:
Qtr/Qtr: NW/SE Section: 23 Township: 6N Range: 67W
Footages: 1780 FSL & 1980 FEL
COUNTY: WELD **STATE:** CO **API #:** 05-123-12283

ENGINEER: JOHN HATCH 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 9 5/8" 36# @ 411' KB Elevation: 4775'
Surface Cmt: 292 sx GL Elevation: 4765'
Long St Csg: 5 1/2" 17.0#, N-80 @ 7287' TD: 7312'
Long St Cmt: 225 sx PBTD: 7242'
Long St Date: 3/23/1985

Plug Back (Sand or CIBP): _____
Perforation Interval (1): Niobrara Perforations 6952' - 6978'
Perforation Interval (2): Codell Perforations 7146' - 7163
Perforation Interval (3): _____
Tubing: 2 3/8" 4.70#, J-55 @ 7134' Rods: _____
Pump: _____
Misc.: _____

PRODUCTION STATUS: _____
COMMENTS: _____

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 2 3/8" tbg and lay down.
- 3) RU WL. RIH w/ CIBP. Set CIBP @ 6902', dump bail 2 sx of cement on top.
- 4) Unland casing. Cut casing off @ 2500'. POOH with casing laying down on trailer.
- 5) RIH w/ workstring to pump 100 sx stub plug where csg was pulled. If maintain circulation, no need to tag plug.
- 6) POOH w/ workstring to 530'. Pump 201 sx shoe plug. Cement to surface.
- 7) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 8) Cut surface casing off 6'-8' below ground.
- 9) Clean up location. RDMOL.