

WORKOVER PROCEDURE

WELL NAME: MOBILE PREMIX I35-06 **DATE:** 2/19/2016
LOCATION:
Qtr/Qtr: SW/NW Section: 35 Township: 6N Range: 66W
Footages: 2032 FNL & 692 FWL
COUNTY: WELD **STATE:** CO **API #:** 05-123-23218

ENGINEER: John Hatch 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8" 24#, J-55 @533' KB Elevation: 4690'
Surface Cmt: 460 sx GL Elevation: 4678'
Long St Csg: 4 1/2" 11.60#, M-80 @ 7508' TD: 7518'
Long St Cmt: 620 sx PBTD: 7462'
Long St Date: 10/21/2005

Plug Back (Sand or CIBP): _____
Perforation Interval (1): CodeII Perforations 7340' - 7356'
Perforation Interval (2): _____
Perforation Interval (3): _____
Tubing: No tubing downhole Rods: _____
Pump: _____
Misc.: _____

PRODUCTION STATUS: _____
COMMENTS: _____

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) RU WL. RIH w/ CIBP. Set CIBP @ 7290', pump 46 sx of cement on top.
- 3) Unland casing. Cut casing off @ 2500'. POOH with casing laying down on trailer.
- 4) RIH w/ workstring to pump 100 sx stub plug where csg was pulled. If maintain circulation, no need to tag plug.
- 5) POOH w/ workstring to 583'. Pump 203 sx shoe plug. Cement to surface.
- 6) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 7) Cut surface casing off 6'-8' below ground.
- 8) Clean up location. RDMOL.