

WORKOVER PROCEDURE

WELL NAME: KUIS C05-02 **DATE:** 3/2/2016

LOCATION: Qtr/Qtr: NW/NE Section: 5 Township: 4N Range: 64W

Footages: 660' FNL & 1960' FEL

COUNTY: WELD **STATE:** CO **API #:** 05-123-16215

ENGINEER: Jonathan Pomerantz 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8" 24# @ 326' KB Elevation: 4724'
Surface Cmt: 220 sx GL Elevation: 4715'
Long St Csg: 2 7/8" 8.7# @ 7081' TD: 7090'
Long St Cmt: 230 sx PBTD: 6932'
Long St Date: 9/23/1992

Plug Back (Sand or CIBP): Sand
Perforation Interval (1): Codell Perforations 6926' - 6938'
Perforation Interval (2): _____
Perforation Interval (3): _____
Tubing: 1 1/4" 2.33# J-55 tbg @ 6899' Rods: _____
Pump: _____
Misc.: _____

PRODUCTION STATUS: _____

COMMENTS: _____

- PROCEDURE:**
- 1) MIRU Workover rig, pump & tank.
 - 2) POOH w/ 1 1/4" tbg and lay down.
 - 3) RU WL. RIH w/ CIBP. Set CIBP @ 6876'. RIH w/ workstring to pump 10 sx on top of CIBP.
 - 4) Unland casing. Cut casing off @ 2500'. POOH w/ casing laying down on trailer.
 - 5) RIH w/ workstring to pump 100 sx stub plug where csg was pulled. If maintain circulation, no need to tag plug.
 - 6) POOH w/ workstring to 530'. Pump 180 sx shoe plug. Cement to surface.
 - 7) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
 - 8) Cut surface casing off 6'-8' below ground.
 - 9) Clean up location. Reclaim location. RDMO.